

Body Shop Report **Arnie Bauer** **Buick GMC** **Cadillac**

Complete On: 9/05/2024

Report Created By:

Jim Perschke

847-975-2324

jperschke@autorisknow.com

Eye wash equipment has not been tested, cleaned and documented weekly.

Date of occurrence: September 05, 2024

Eyewash station is completely empty. also needs signage above unit.



Other additional electrical issues noted.

Date of occurrence: September 05, 2024

electric motor cover is missing with wires exposed



Holes not filled or blanks being used on electrical panels

Date of occurrence: September 05, 2024

found vacant hole on side of electric panel.



No signs posted warning of "Automatic Start" feature of the compressors.

Date of occurrence: September 05, 2024

Compressor needs automatic start signage.



Secondary containers filled with chemicals are not properly labeled.

Date of occurrence: September 05, 2024

found secondary containers with liquid needing contents label



Fire extinguishers are not easily accessible.

Date of occurrence: September 05, 2024

Extinguishers need proper mounting and signage above units.



Floor openings, gaps, in excess of 2.25" wide are not covered with hinged flaps.

Ladders not stored properly, needs chained off on any ladder over 8ft.