

# OSHA Report **Brilliance** **Subaru**

Complete On: 8/14/2024

Report Created By:

Jim Perschke

847-975-2324

[jperschke@autorisknow.com](mailto:jperschke@autorisknow.com)

**Hoists are not being maintained within mfg. specs, and inspected and serviced AND documented under the mfg. suggested frequency. Usually annually.**

Date of occurrence: August 14, 2024

*Noticed Hoist inspection sticker shows annual inspection is overdue March 2024*



---

**All tanks holding flammable material are not properly grounded.**

Date of occurrence: August 14, 2024

*50 gallon steel drum w/ flammable liquid needs to be grounded*



---

**There is no proper spacing on grinders; Tool rest 1/8" from grinding wheel. Tongue plate 1/4" from grinding wheel.**

Date of occurrence: August 14, 2024

*Need tool rest adjustment on grinder*



**The fire extinguishers have not had their annual inspection and are not properly identified and fully charged.**

Date of occurrence: August 14, 2024

*Found 1 Fire extinguisher overdue for inspection The rest are good thru October*



**All gas cylinders are not stored and tied off properly.**

**Ladders not stored properly, needs chained off on any ladder over 8 ft.**

**Fire Extinguisher missing or not properly mounted in dispensing area**