

2151



Units Affected by Component Failure Type

of the 7 theorem by Compenient 1 and 10 Type												
Manufacturer	AIR BAGS	BACK OVER PREVENTION	CHILD SEAT	COMMUNICATION	ELECTRICAL SYSTEM	ELECTRONIC STABILITY CONTROL	ENGINE	ENGINE AN				
Ford Motor Company	13464138	1403279	39807		4849153	1948	795847					
General Motors, LLC	17641729	105430	246456		23882865	1121765	318374					
Chrysler (FCA US, LLC)	28428816	685238	1425991		14692184	825820	124027					
Takata (TK Global, LLC)	87467531											
Toyota Motor Engineering & Manufacturing	19211557	63744	75316		1495703	867106	176013					
Honda (American Honda Motor Co.)	27915764	2520704			7435923	91920	286					
Nissan North America, Inc.	9434771	1276377	138232		3179204							
PENNZOIL-QUAKER STATE COMPANY												
Hyundai Motor America	3076851				874625	187528	1003686					
Bridgestone Americas Tire Operations												
Volkswagen Group of America, Inc.	4440737	257645	466		2129613	135683	4526					
Subaru of America, Inc.	3188550	33308			1821935	5896						
Kia America, Inc.	1665259		90865		1023772	7619	935652					
BMW of North America, LLC	3701583	276817	228606		1762247	16	50772					
Mercedes-Benz USA, LLC	2392905	478192	7064	1553104	690921	54216	9791					
Dorel Juvenile Group			8951550									
Total	234891619	7910377	38098747	1573041	73810632	4087580	3772091	Y				
<		<u> </u>						>				



Corrective Actions Frequency by Action Taken Frequency Component Component 14K **⊞** EQUIPMENT 8483 All **⊞ ELECTRICAL SYSTEM** 5031 **⊞** STEERING 3309 12K **⊞** SUSPENSION 3096 2741 2641 10K **⊞** AIR BAGS 2590 **THE STRUCTURE** 2534 Frequency 8K 2472 **ENGINE AND ENGINE COOLING** 2119 2086 **EXTERIOR LIGHTING** 6K 2014 **BERVICE BRAKES, AIR TIRES** 1959 **EXECUTE** SEAT BELTS 1934 4K ∃ SEATS 1407 **⊞ VISIBILITY** 1364 2K **WHEELS** 1005 **⊞ EQUIPMENT ADAPTIVE/MOBILITY** 785 731 0K 714 service unit inspect unit install part repair fault modify part notify remove adjust part refund retrofit part **TRAILER HITCHES** 642 unit/part owner part software owner **Action Taken B** PARKING BRAKE 618 2023 1998 Component **Workflow Analysis** All Funnel: Top 20 Key Workflows by Volume Affected 100% notify owner, replace unit/part, service unit 73M replace unit/part 58M notify owner, replace unit/part 50M notify owner, service unit 46M install part, replace unit/part, service unit 35M install part, notify owner, service unit inspect unit, notify owner, replace unit/part, service unit 31M 25M install part, notify owner, replace unit/part, service unit 24M install part, replace unit/part service unit 22M 22M install part 19M install part, notify owner notify owner, repair fault, replace unit/part, service unit 18M notify owner 15M 15M inspect unit, notify owner, service unit inspect unit, replace unit/part 14M 12M notify owner, reprogram software, service unit 10M notify owner, repair fault, replace unit/part 10M replace unit/part, service unit inspect unit, install part, replace unit/part 9M 5.5% Most Common Workflows by Event Count, Component Component notify owner, replace unit/part, service unit AIR BAGS replace unit/part BACK OVER PREVENTION notify owner, replace unit/part CHILD SEAT notify owner, service unit COMMUNICATION inspect unit, notify owner, replace unit/part, ... install part, notify owner, service unit ELECTRICAL SYSTEM Key Workflows notify owner ELECTRONIC STABILITY CONTROL install part ENGINE inspect unit, notify owner, service unit ENGINE AND ENGINE COOLING inspect unit, replace unit/part EQUIPMENT notify owner, repair fault repair fault, replace unit/part, service unit EQUIPMENT ADAPTIVE/MOBILITY inspect unit, notify owner, replace unit/part EXTERIOR LIGHTING replace unit/part, service unit FORWARD COLLISION AVOIDANCE modify part, notify owner, service unit FUEL SYSTEM, DIESEL notify owner, repair fault, replace unit/part, s... FUEL SYSTEM, GASOLINE install part, notify owner 4K ● FUEL SYSTEM, OTHER 0K 2K 3K Count of Recall Events

Raw Data

Report Received Date	NHTSA ID	Manufacturer	Mfr Campaign Number	Recall Type	Component	Subject	Recall Description
10 March 2023	23V161000	Kibbi, LLC	NR (Not Reported)	Vehicle	LATCHES/LOCKS/LINKAGES	Entry Door Latch Failure	Kibbi, LLC (Kibbi) is r
10 March 2023	23V162000	Ford Motor Company	23S12	Vehicle	SERVICE BRAKES, HYDRAULIC	Front Brake Hoses May Rupture	Ford Motor Company
10 March 2023	23V160000	Ford Motor Company	23C04	Vehicle	EXTERIOR LIGHTING	Inoperative Trailer Taillights/FMVSS 108	Ford Motor Company vehicles fail to comply
10 March 2023	23V164000	Ford Motor Company	23S11	Vehicle	SERVICE BRAKES, HYDRAULIC	Rear Caliper Bolts Not Tightened Correctly	Ford Motor Company
10 March 2023	23V165000	Ford Motor Company	23C05	Vehicle	BACK OVER PREVENTION	Rearview Camera Malfunction/FMVSS 111	Ford Motor Company a backing event has
10 March 2023	23V163000	Ford Motor Company	23\$10	Vehicle	VISIBILITY	Windshield Wipers may Fail	Ford Motor Company
09 March 2023	23E020000	Gilbarco, Inc.	NR (Not Reported)	Equipment	ELECTRICAL SYSTEM	Cracked Capacitor May Cause Overheating	Gilbarco, Inc. (Gilbarc
09 March 2023	23E019000	Chrysler (FCA US, LLC)	21A	Equipment	SERVICE BRAKES, HYDRAULIC	Hydraulic Control Unit Malfunction	Chrysler (FCA US, Ll circuit and illuminate
09 March 2023	23V158000	Honda (American Honda Motor Co.)	NDA, QDB, BDC, MDD	Vehicle	SEAT BELTS	Seat Belt Buckle May Not Latch	Honda (American Ho may cause the seat b
09 March 2023	23V159000	Rivian Automotive, LLC	FSAM-1185	Vehicle	AIR BAGS	Side Curtain Air Bag Improperly Secured	Rivian Automotive, Ll
08 March 2023	23E018000	AROW Global Corp	NR (Not Reported)	Equipment	STRUCTURE	Emergency Exit Window Latch May Fail/FMVSS 217	AROW Global Corp (and allow the window
08 March 2023	23V154000	Navistar, Inc.	23506	Vehicle	ELECTRICAL SYSTEM	Battery Box May Detach	Navistar, Inc. (Navista
08 March 2023	23V157000	Eveland's Inc.	NR (Not Reported)	Vehicle	EQUIPMENT	Damaged Cooktop Control Valves May Leak Gas	Eveland's Inc. (Evela
08 March 2023	23V153000	Navistar, Inc.	23505	Vehicle	POWER TRAIN	DRIVESHAFT SEPARATION	Navistar, Inc. (Navista separation.
08 March 2023	23V156000	Spartan Fire, LLC	23007	Vehicle	POWER TRAIN	Fire Truck Water Pump May Fail	Spartan Fire LLC (Sp needed to initiate the
08 March 2023	23V152000	Bentley Motors, Inc.	RE23/03 (RC68)	Vehicle	AIR BAGS	Seat Air Bag May Tear/FMVSS 214 & 208	Bentley Motors, Inc. (requirements of Fede
08 March 2023	23V155000	Ford Motor Company	23\$09	Vehicle	STEERING	Steering Wheel May Lock-Up While Driving	Ford Motor Company
07 March 2023		SAF-Holland	NR (Not Reported)	Equipment	SUSPENSION	Lower Control Arm May Fail	SAF-Holland is recall
07 March 2023		Grand Design RV, LLC	910033	Vehicle	TIRES	Incorrect Tire Information on Label/FMVSS 110	Grand Design RV, LL requirements of Fede
07 March 2023		Kia America, Inc.	SC263	Vehicle	AIR BAGS	Side Curtain Air Bags May Not Deploy Properly	Kia America, Inc. (Kia
07 March 2023		Terex Advance Mixer, Inc.	NR (Not Reported)	Vehicle	STEERING	Steer Axle Fasteners Not Tightened Properly	Terex Advance Mixer separation of the axle
06 March 2023	23V146000	Triumph Motorcycles America, Ltd.	SRAN 606	Vehicle	SERVICE BRAKES, HYDRAULIC	Brake Disc May Detach	Triumph Motorcycles
06 March 2023	23V147000	Newell Coach Corp.	NR (Not Reported)	Vehicle	EXTERIOR LIGHTING	Brake Lights May Fail to Illuminate	Newell Coach Corp.