


Phase-jump method stress map



Guide used in slide discussion: 0.05 Hz RMSE. Gray cells denote unavailable finite values.