EMERGENCY SHUTDOWN PROCEDURE FOR ARCTIC OPERATIONS

EMERGENCY SHUTDOWN PROCEDURE FO

Document ID: ESD-ARC-2024-001

Version: 3.1

Effective Date: January 15, 2024

Last Review: January 1, 2024

Document Owner: Polar Dynamics Robotics, Inc.

1. PURPOSE AND SCOPE

1 This Emergency Shutdown Procedure ("Procedure") establishes ma

2 This Procedure applies to all Company AMRs deployed in environment
2. DEFINITIONS
1 "Emergency Shutdown" means the immediate cessation of AMR op
2 "BlueCore(TM) System" refers to the Company's proprietary cold-er
3 "Critical Temperature Threshold" means the temperature at which e 4 "Safety Perimeter" means the designated clear zone of 3 meters rad
3. EMERGENCY SHUTDOWN TRIGGERS
1 Automatic shutdown shall be initiated under any of the following cor

- a) Internal temperature sensors detect readings below Critical Tempe Threshold
- b) BlueCore(TM) power cell capacity drops below 15%
- c) Navigation system reports three consecutive positioning errors
- d) Detection of unauthorized access to core systems
- e) Emergency Stop (E-Stop) button activation
- 2 Manual shutdown may be initiated by authorized personnel through

4. SHUTDOWN SEQUENCE

- 1 Upon trigger activation, the AMR shall:
- a) Immediately cease all current operations
- b) Transmit emergency status to Central Control

- c) Engage mechanical braking systems
- d) Power down non-essential systems
- e) Activate emergency locator beacon
- f) Initialize BlueCore(TM) hibernation mode
- 2 The shutdown sequence must complete within 30 seconds of initiati

5. SAFETY PROTOCOLS

- 1 Personnel Requirements
- a) Only certified technicians may approach AMR during shutdown
- b) Minimum of two personnel must be present
- c) Arctic-rated PPE must be worn
- d) Emergency communication devices must be carried

2 Safety Perimeter

- a) Establish and maintain Safety Perimeter until shutdown complete
- b) Place warning markers at perimeter boundaries
- c) Monitor for unauthorized entry
- d) Maintain perimeter until all-clear signal received

6. RECOVERY PROCEDURES

- 1 Post-Shutdown Assessment
- a) Conduct visual inspection for physical damage
- b) Download system logs within 1 hour of shutdown
- c) Document environmental conditions
- d) Verify BlueCore(TM) system integrity

- 2 Restagt Authorization
- a) Chief Robotics Officer or designee must authorize restart
- b) Complete safety checklist (Form ESD-CHK-001)
- c) Verify environmental conditions within operational parameters
- d) Confirm system diagnostics clear

7. REPORTING REQUIREMENTS

- 1 Within 24 hours of any emergency shutdown, submit detailed incide
- a) Date, time, and location
- b) Triggering conditions
- c) Personnel involved
- d) System logs and diagnostic data

- f) Corrective actions taken
- 2 Maintain shutdown log in compliance with ISO 9001:2015 requirement

8. COMPLIANCE AND TRAINING

- 1 All operational personnel must complete annual emergency shutdow
- 2 Quarterly shutdown drills required for all arctic deployment locations
- 3 Procedure review required annually or upon significant system mod

9. LEGAL DISCLAIMER

This Procedure is proprietary to Polar Dynamics Robotics, Inc. and co

confidential information. Unauthorized distribution or reproduction is prohibited. The Company reserves the right to modify this Procedure notice. While this Procedure is designed to maximize safety, the Compon warranties regarding the effectiveness of these procedures under circumstances.

10. AUTHORIZATION

APPROVED BY:

Dr. James Barrett

Chief Robotics Officer

Polar Dynamics Robotics, Inc.

Date: _

Sarah Nordstrom

Chief Operating Officer

Polar Dynamics Robotics, Inc.

Date: _

