










TITLE: Motherboard - PWM Driver		REV: 2.0
EasyEDA	Company:	Sheet: 1/4
	Date: 2020	Drawn By: joelamichaelis




Added external reset because blue pill's onboard reset button is inaccessible the way it gets mated to the motherboard from the bottom.

TITLE: Motherboard - Micro		REV: 2.0
EasyEDA	Company:	Sheet: 2/4
	Date: 2020	Drawn By: joelamichaelis



TITLE: Motherboard - Peripherals		REV: 2.0
EasyEDA	Company:	Sheet: 3/4
	Date: 2020	Drawn By: joelamichaelis



Untested but load switches were added as a cost reduction.
Paralleled 2 to overcome current limit. Not sure this is ideal.

TITLE: Motherboard - PSU		REV: 2.0
EasyEDA	Company:	Sheet: 4/4
	Date: 2020	Drawn By: joelamichaelis