

## CROCHIP dsPIC30F6010 to dsPIC30F6010A

## dsPIC30F6010 to dsPIC30F6010A Migration Guidelines

**Note:** This device has been designed to perform to the parameters of its data sheet. It has been tested to an electrical specification designed to determine its conformance with these parameters. Due to process differences in the manufacture of this device, the dsPIC30F6010A may have different performance characteristics than its earlier version, dsPIC30F6010. These differences may cause this device to perform differently in your application than the earlier version of this device.

**Note:** You should verify that the device oscillator starts and performs as expected. Adjusting the loading capacitor values and/or the oscillator mode may be required.

#### **GENERAL INFORMATION**

This document provides an overview of considerations for migrating from dsPIC30F6010 to dsPIC30F6010A devices. If you are undertaking this migration, it is recommended that you download data sheets and errata documents on these devices from our web site, www.microchip.com.

Most errata for the dsPIC30F30F6010 Rev. B1/B2 silicon have been fixed in the dsPIC30F30F6010A Rev. A2 silicon. The specific device errata documents are listed here for reference:

- dsPIC30F6010 Rev. B1 errata DS80182
- dsPIC30F6010 Rev. B2 errata DS80195

Appendix B of the "dsPIC30F30F6010A/6015 Data Sheet" (DS70150) provides device comparison summaries between dsPIC30F6010 and dsPIC30F6010A devices.

Appendix C of the "dsPIC30F30F6010A/6015 Data Sheet" (DS70150) provides device migration information between dsPIC30F6010 and dsPIC30F6010A devices.

Respective data sheets and errata documents for both devices are posted on Microchip's web site, www.microchip.com.

In most cases, code developed for the dsPIC30F6010 devices is directly portable to the dsPIC30F6010A devices, with the exceptions summarized in the "Peripherals" section.

#### **CODE COMPATIBILITY**

For the most part, dsPIC30F code developed with the MPLAB® C30 C Compiler and MPLAB ASM30 Assembler is directly portable between the dsPIC30F6010 and dsPIC30F6010A devices. However, in some cases small changes may be required depending on which features have been enhanced. To migrate source code to the dsPIC30F6010A device, perform these two steps:

- Include the appropriate dsPIC30F6010A device header (.h) and include (.inc) files in the source code files.
- Remove any work arounds implemented in source code or MPLAB C30 command line options for errata described in the "dsPIC30F6010 Rev. B2 Silicon Errata" (DS80195B) document.

Note: See "Recommended Procedure for Migrating from dsPIC30F6010 to dsPIC30F6010A" on page 4.

#### OSCILLATOR OPERATION

Several oscillator modes have been added to the dsPIC30F6010A device:

- FRC with x4, x8 and x16 PLL mode
- HS/2 with x4, x8 and x16 PLL mode
- HS/3 with x4, x8 and x16 PLL mode

In support of the Fast RC Oscillator (FRC), the OSCTUN Special Function Register (SFR) has been added. This register includes six FRC tuning bits (TUN<5:0>). There are no code or operational compatibility issues to address for this new feature.

Another important change deals with the OSCCON SFR. Bits have been added to both the COSC and NOSC functional definitions. Use the dsPIC30F6010A device header and include files to achieve code portability with the OSCCON SFR.

Note: Oscillator operation should be verified to ensure that it starts and performs as expected. You may need to adjust the load capacitor and/or the oscillator mode to achieve the proper values.

# DEVICE CONFIGURATION REGISTERS

In support of the new oscillator modes, the FOSC Configuration register has been modified. The dsPIC30F6010A device header and include files provide the updated bit field definitions and macros for the device Configuration registers. Please refer to these new macros when embedding specific device configuration information in the C and Assembler source files.

#### **PERIPHERALS**

Some peripheral changes have been made in regards to specific errata fixes and additional features. No new peripheral modules have been added.

<u>Low-Voltage Detect (LVD)</u> – This module is not available on the dsPIC6010A device.

Motor Control Pulse-Width Modulation (MCPWM) – An additional control bit has been added to the module to allow additional functionality. The Immediate Update Enable (IUE) control bit is added to the PWMCON2 SFR. Refer to the "dsPIC30F Family Reference Manual" (DS70046) for additional details.

Quadrature Encoder Interface (QEI) – The control bits in the DFLTCON SFR have changed to allow additional functionality. Refer to the "dsPIC30F Family Reference Manual" (DS70046) for additional details.

<u>Device Oscillator</u> – The device oscillator feature set has been enhanced to provide additional flexibility. The new oscillator modes are presented in Section 21.0 "System Integration" of the "dsPIC30F6010A/6015 Data Sheet" (DS70150). In support of the Fast RC oscillator (FRC), the OSCTUN Special Function Register (SFR) has been added. This register includes six FRCs tuning bits (TUN<5:0>). The new oscillator modes are supported by use of the respective dsPIC30F6010A device header (.h), linker (.gld) and include (.inc) files in the source code files. Refer to the "dsPIC30F6010A/6015 Data Sheet" (DS70150) for more information. The following oscillator modes have been added:

- HS/2 x4, x8 and x16PLL mode
- HS/3 x4. x8 and x16PLL mode
- FRC x4, x8 and x16PLL mode

#### **ELECTRICAL CHARACTERISTICS**

Table 1 below presents a comparison of the operating MIPS vs. voltage between the dsPIC30F6010A and dsPIC30F6010 devices.

The dsPIC30F6010 and dsPIC30F6010A devices are designed using the same process technology. Therefore, the DC and AC electrical specifications are closely related. Exceptions to this are the Run, Idle and Sleep currents which should slightly improve. Consult the data sheets for further information.

TABLE 1: OPERATING MIPS VS. VOLTAGE CHARACTERISTICS

VDD	Temp.	Maximum MIPS			
Range (V)	Range (°C)	dsPIC30F6010A-30I	dsPIC30F6010-30I	dsPIC30F6010A-20E	dsPIC30F6010-20E
4.5-5.5	-40 to +85	30	30	_	_
4.5-5.5	-40 to +125	_	_	20	20
3.0 to 3.6	-40 to +85	20	15	_	_
3.0 to 3.6	-40 to +125	_	_	15	10
2.5 to 3.0	-40 to +85	10	7.5	_	_

# PACKAGE MIGRATION CONSIDERATIONS

The dsPIC30F6010 device is available in a 14mm x 14mm TQFP package. The dsPIC30F6010A device is available in the same 14mm x 14mm package, as well as a 12mm x 12mm package that offers additional space savings in the customer's board.

# DEVELOPMENT TOOLS AND BOARDS

MPLAB IDE, MPLAB C30, MPLAB ICD 2 and MPLAB PM3 tools support both the dsPIC30F6010 and dsPIC30F6010A. See Table 2 below for information on version support.

MPLAB ICE 4000 supports the dsPIC30F601XA devices, however the operation of the MPLAB ICE 4000 tool is limited to dsPIC30F6010 functional operation, including all device errata listed in DS80195.

A Plug-In-Module (PIM) (MA30015) is available for the dsPIC30F6010A device. This PIM can replace the MA300013 PIM containing the dsPIC30F6010 device.

The dsPIC30F6010A is supported by all development boards that support the dsPIC30F6010 device. These boards include the dsPICDEM™ MC1, dsPICDEM 1.1, and dsPICDEM 80-pin Starter Development Board.

Note: When using the dsPIC30F6010A device on the dsPICDEM-MC1 motor control development board, the user must short resistors R37 and R40 to ensure reliable communication with the MPLAB ICD 2 in-circuit debugger.

TABLE 2: DEVELOPMENT TOOL DEVICE SUPPORT

Development Teels	Device Support			
Development Tools	dsPIC30F6010A	dsPIC30F6010		
MPLAB <sup>®</sup> IDE	MPLAB IDE 7.21 or later	All current releases		
MPLAB C30	MPLAB C30 1.32 or later	MPLAB C30 1.10 and later		
MPLAB ICD 2 Programmer/Debugger	Yes	Yes		
MPLAB REAL ICE Emulator/Debugger	Yes	Yes		
MPLAB PM3 Device Programmer	Yes	Yes		
MPLAB ICE 4000	Yes <sup>(1)</sup>	Yes <sup>(1)</sup>		

**Note 1:** MPLAB ICE 4000 supports the dsPIC30F601XA devices, however the operation of the MPLAB ICE 4000 tool is limited to dsPIC30F6010 functional operation, including all device errata listed in DS80195.

# RECOMMENDED PROCEDURE FOR MIGRATING FROM dsPIC30F6010 TO dsPIC30F6010A

Follow this process to migrate from the dsPIC30F6010 to the dsPIC30F6010A:

#### **Prepare**

 Carefully read "dsPIC30F6010A/6015 Rev A2 Silicon Errata" (DS80258) to ensure there is no errata that will constrain your ability to migrate from the dsPIC30F6010 to the dsPIC306010A.

#### **Recompile Software**

- Reconfigure your MPLAB IDE workspace for the dsPIC30F6010A (MPLAB IDE > Configure > Select Device > dsPIC30F6010A)
- Replace Device Header files and Linker scripts (default file location c:\Program Files\MPLAB C30\Support\)
- Change Device Configuration bits as appropriate (MPLAB IDE > Configure > Configuration Bits)
- Remove software work arounds in your dsPIC30F6010 project that are not needed for dsPIC30F6010A silicon. If necessary, refer to "dsPIC30F6010 Rev. B1 Silicon Errata" (DS80182) and "dsPIC30F6010 Rev. B2 Silicon Errata" (DS80195) to help identify work around items.

Note: To take advantage of new features added to dsPIC30F6010A devices, refer to Appendix B. "Device Comparisons" and Appendix C. "Migration from dsPIC30F6010 to dsPIC30F6010A" in the "dsPIC30F6010A/6015 Data Sheet" (DS70150).

#### Set up Hardware

 Solder a dsPIC30F6010A Rev. A2 device on your target board. The pins are compatible with the dsPIC30F6010, so no board level changes are required.

Alternatively, use a dsPIC30F6010A PIM (MA300015)

#### **Test**

7. Run your test programs.

#### APPLICATION LIBRARIES

All advanced application libraries developed for the dsPIC30F6010 device are supported on the dsPIC30F6010A devices as well.

#### REFERENCE DOCUMENTS

The following documents are available on our web site, www.microchip.com, and are recommended reading:

- "dsPIC30F6010 Data Sheet" (DS70119)
- "dsPIC30F6010A/6015 Data Sheet" (DS70150)
- "dsPIC30F Family Reference Manual" (DS70046)
- "dsPIC30F6010 Rev. B1 Silicon Errata" (DS80182)
- "dsPIC30F6010 Rev. B2 Silicon Errata" (DS80195)
- "dsPIC30F6010A Rev. A2 Silicon Errata" (DS80258)

#### **APPENDIX A: REVISION HISTORY**

#### Revision A (March 2006)

Original version of the document.

#### **Revision B (November 2006)**

This revision reflects these changes:

- Adds MPLAB REAL ICE In-Circuit Emulator to development tools
- Adds recommended procedure for migrating from dsPIC30F6010 to dsPIC30F6010A
- Adds "dsPIC30F6010A Rev. A2 Silicon Errata" (DS80258) to Reference Documents

NOTES:

#### Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not
  mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, Keeloo, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AmpLab, FilterLab, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Linear Active Thermistor, Mindi, MiWi, MPASM, MPLIB, MPLINK, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

 $\ensuremath{\mathsf{SQTP}}$  is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2006, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM

CERTIFIED BY DNV

ISO/TS 16949:2002

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona, Gresham, Oregon and Mountain View, California. The Company's quality system processes and procedures are for its PIC® 8-bit MCUs, KEELoQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



## WORLDWIDE SALES AND SERVICE

#### **AMERICAS**

**Corporate Office** 

2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277

http://support.microchip.com

Web Address: www.microchip.com

Technical Support:

Atlanta

Alpharetta, GA Tel: 770-640-0034 Fax: 770-640-0307

**Boston** Westborough, MA Tel: 774-760-0087

Fax: 774-760-0088 Chicago

Itasca, IL

Tel: 630-285-0071

Fax: 630-285-0075

Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Farmington Hills, MI Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

Kokomo, IN Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608

Santa Clara

Santa Clara, CA Tel: 408-961-6444 Fax: 408-961-6445

**Toronto** 

Mississauga, Ontario, Canada

Tel: 905-673-0699 Fax: 905-673-6509

#### ASIA/PACIFIC

Asia Pacific Office

Suites 3707-14, 37th Floor Tower 6, The Gateway Habour City, Kowloon Hong Kong

Tel: 852-2401-1200 Fax: 852-2401-3431

Australia - Sydney

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8528-2100 Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511 Fax: 86-28-8665-7889

China - Fuzhou

Tel: 86-591-8750-3506 Fax: 86-591-8750-3521

China - Hong Kong SAR

Tel: 852-2401-1200 Fax: 852-2401-3431

China - Qingdao

Tel: 86-532-8502-7355 Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533 Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829 Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8203-2660 Fax: 86-755-8203-1760

China - Shunde

Tel: 86-757-2839-5507 Fax: 86-757-2839-5571

China - Wuhan

Tel: 86-27-5980-5300 Fax: 86-27-5980-5118

China - Xian

Tel: 86-29-8833-7250 Fax: 86-29-8833-7256

#### ASIA/PACIFIC

India - Bangalore

Tel: 91-80-4182-8400 Fax: 91-80-4182-8422

India - New Delhi

Tel: 91-11-4160-8631 Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-2566-1512 Fax: 91-20-2566-1513

Japan - Yokohama

Tel: 81-45-471-6166 Fax: 81-45-471-6122

Korea - Gumi

Tel: 82-54-473-4301 Fax: 82-54-473-4302

Korea - Seoul

Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934

Malaysia - Penang Tel: 60-4-646-8870

Fax: 60-4-646-5086

Philippines - Manila

Tel: 63-2-634-9065 Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870 Fax: 65-6334-8850 Taiwan - Hsin Chu

Tel: 886-3-572-9526

Fax: 886-3-572-6459

Taiwan - Kaohsiung Tel: 886-7-536-4818

Fax: 886-7-536-4803

Taiwan - Taipei

Tel: 886-2-2500-6610 Fax: 886-2-2508-0102

Thailand - Bangkok Tel: 66-2-694-1351

Fax: 66-2-694-1350

#### **EUROPE**

Austria - Wels

Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen

Tel: 45-4450-2828 Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany - Munich

Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Italy - Milan

Tel: 39-0331-742611 Fax: 39-0331-466781

Netherlands - Drunen Tel: 31-416-690399

Fax: 31-416-690340

Spain - Madrid

Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 **UK - Wokingham** 

Tel: 44-118-921-5869 Fax: 44-118-921-5820

10/19/06