

Fryers: Frymaster and Pitco Models (Electric Only)

Check Position of Hi-Limit Probes

Frequency

Weekly

Models

Frymaster and Pitco Models (Electric only)

Estimated Time to Complete

15 Minutes

Health & Safety Hazards

Food Safety



Wash and dry hands **after** performing this task



Inspect equipment. Do not use if damaged

Check for the Following

NB The following PM Test should be completed when fryer vats have had McDonald's cooking oil dropped

- 1 Hi limit probe is securely clipped to the element
- 2 No visible signs of damage or being misshapen
- 3 Repeat the check for all fry vats

Caution: Hi Limit probe must be submerged in McDonalds Cooking Oil whilst Fryer is on.

NB If a Hi Limit probe is damaged or missing switch the vat off – Do not use. Contact your [Service Company](#).

