Inspection report

AV-26-004267 | Site visit 2026-09-19 | Report revision 1

INSURED	Lantern Yard Bistro Ltd
SITE	Unit 7, Lantern Yard Retail Court, Westbridge
REPORTED EVENT	Reported contained cooking-area fire with smoke contamination
INSPECTING ADJUSTER	Priya Lane

1. Reported circumstances

The restaurant manager reported a contained incident during evening preparation. The kitchen was closed and electrical equipment was not returned to service pending inspection. The notification lists no injuries. Opening hours and any trading loss remain subject to separate evidence.

2. Observations and limitations

Soot is visible on the extraction hood, filters and nearby ceiling. Local ceiling discoloration and deposits are shown in the photographic schedule. Photographs do not establish the ignition source, the condition of concealed ductwork or whether the extraction motor is repairable.

See the embedded annotated photo exhibit and case-specific location sketch. Both are original synthetic scenario exhibits; they do not establish cause, timing, liability or coverage.

Preliminary repair scope

AV-26-004267 | Revision 1 | 2026-09-19 | USD; tax excluded

Item / description	Qty	Unit	Rate	Amount
Isolation and protective works	1	LS	2,400.00	2,400.00
Specialist soot cleaning	160	m2	45.00	7,200.00
Replace affected ceiling tiles	48	m2	90.00	4,320.00
Extraction hood service allowance	1	LS	6,800.00	6,800.00
Electrical testing	1	LS	2,880.00	2,880.00
Reinstatement and decoration	1	LS	9,000.00	9,000.00
PRELIMINARY TOTAL				**32,600.00**

Scope qualifications


Quantities are provisional. Reserves, preliminary repair estimates, later proposals and any eventual payment are different measures. No completed work, cause or insurer approval is certified.

Obtain the extraction-system service log and specialist duct inspection. Do not equate cosmetic smoke deposits with confirmed equipment failure. Keep cleaning and replacement scopes separate until the specialist report is received.

Annotated photo exhibit

AV-26-004267 | Synthetic scenario photos; original JPGs retained separately

PHOTO EXHIBIT | AV-26-004267





A - Visible hood / ceiling soot deposits

B - Filter staining; concealed duct not inspected

Synthetic photos. Annotations describe appearances, not cause, timing, liability or coverage.

How to read this exhibit

Marks A and B refer to visible appearances only. Compare the embedded images with the inspection narrative and the separate original JPGs. Not every visually useful detail is transcribed into the report text.


These are generated scenario images, not independently dated field photographs. A later image cannot prove an earlier event sequence or reveal concealed conditions.

Location and evidence sketch

AV-26-004267 | Embedded case-specific diagram - not to scale

KITCHEN EXTRACTION / CEILING SKETCH

AV-26-004267 | 2026-09-19 | Schematic - not to scale



Visible soot area shown in red; ignition source remains unconfirmed.

Original fictional claim exhibit. Red marks = observed appearance / reported area; dashed lines = uncertainty.

Interpretation and unresolved evidence

The kitchen sketch distinguishes the visible hood and ceiling appearance from the uninspected concealed duct. The dashed route is not an established ignition or spread path.

The first contractor scope allows cleaning of the extraction hood. The later proposal replaces the motor and controls without a diagnostic test report. That additional scope is not yet reconciled.