Inspection report

AV-26-004318 | Site visit 2026-09-24 | Report revision 1

INSURED	Harbor Route Delivery Services Inc
SITE	Depot B, Harbor Route Distribution Yard, Northport
REPORTED EVENT	Rear-left damage to a delivery van reported after a depot maneuver
INSPECTING ADJUSTER	Alex Rowan

1. Reported circumstances

The fleet coordinator reported damage to unit HRD-17 after a reversing maneuver in the depot. The driver description and depot supervisor email differ on the sequence of movements. There is no agreed liability position and no invoice for completed repair.

2. Observations and limitations

The rear-left tail-light lens is cracked and the adjacent black bumper is scuffed and locally displaced. No underbody, sensor calibration or concealed structural condition can be established from the supplied exterior photographs.

See the embedded annotated photo exhibit and case-specific location sketch. Both are original synthetic scenario exhibits; they do not establish cause, timing, liability or coverage.

Preliminary repair scope

AV-26-004318 | Revision 1 | 2026-09-24 | USD; tax excluded

Item / description	Qty	Unit	Rate	Amount
Rear-left lamp assembly	1	each	485.00	485.00
Rear bumper and mounting set	1	each	1,250.00	1,250.00
Body and paint labor	18	hours	110.00	1,980.00
Electrical and sensor checks	4	hours	95.00	380.00
Paint materials	1	LS	495.00	495.00
Repairer access and alignment work	1	LS	2,250.00	2,250.00
PRELIMINARY TOTAL				**6,840.00**

Scope qualifications

Quantities are provisional. Reserves, preliminary repair estimates, later proposals and any eventual payment are different measures. No completed work, cause or insurer approval is certified.

Obtain the depot incident log, the full repairer’s revised scope and any available original CCTV. The message forwarding the access instructions contains an attachment that is not stored separately in the claim folder.

Annotated photo exhibit

AV-26-004318 | Synthetic scenario photos; original JPGs retained separately

PHOTO EXHIBIT | AV-26-004318





A - Rear-left bumper appearance

B - Cracked lamp lens; concealed parts unverified

Synthetic photos. Annotations describe appearances, not cause, timing, liability or coverage.


How to read this exhibit

Marks A and B refer to visible appearances only. Compare the embedded images with the inspection narrative and the separate original JPGs. Not every visually useful detail is transcribed into the report text.

These are generated scenario images, not independently dated field photographs. A later image cannot prove an earlier event sequence or reveal concealed conditions.

Location and evidence sketch

AV-26-004318 | Embedded case-specific diagram - not to scale



Interpretation and unresolved evidence

The vehicle sketch identifies the reported rear-left lamp and bumper area. Concealed damage and sensor condition remain unverified; the sketch is not a reconstruction of vehicle movements.

The original estimate is 6,840.00. A later email quotes 7,420.00 including sensor checks, but supplies no replacement estimate PDF. Preserve both amounts and their source dates.