Inspection report

AV-26-004507 | Site visit 2026-10-16 | Report revision 1

INSURED	Rivermark Fabrication Works Ltd
SITE	Workshop 3, Rivermark Industrial Estate, Eastfield
REPORTED EVENT	Reported workshop water ingress with affected stock and equipment
INSPECTING ADJUSTER	Elena Brooks

1. Reported circumstances

The workshop manager reported water at the north wall and low-level wetting to cartons stored beside it. A later contractor proposal was supplied as a PDF attachment to an email. The manager describes rainfall, while the contractor mentions a possible local pipe issue. No cause has been established.

2. Observations and limitations

A low brown water mark is visible on the workshop wall and nearby cardboard cartons show moisture damage. A small pump is present. The photographs alone do not prove ingress route, duration, machinery failure or ownership/value of the affected stock.

See the embedded annotated photo exhibit and case-specific location sketch. Both are original synthetic scenario exhibits; they do not establish cause, timing, liability or coverage.

Preliminary repair scope

AV-26-004507 | Revision 1 | 2026-10-16 | USD; tax excluded

Item / description	Qty	Unit	Rate	Amount
Emergency extraction and drying	1	LS	6,200.00	6,200.00
Affected wall and floor finishes	160	m2	85.00	13,600.00
Stock handling and segregation	1	LS	4,800.00	4,800.00
Machinery cleaning allowance	1	LS	14,200.00	14,200.00
Disposal allowance	1	LS	2,800.00	2,800.00
Inspection and contractor coordination	1	LS	7,000.00	7,000.00
			PRELIMINARY TOTAL	**48,600.00**

Scope qualifications

Quantities are provisional. Reserves, preliminary repair estimates, later proposals and any eventual payment are different measures. No completed work, cause or insurer approval is certified.

Reconcile the contractor’s revised PDF proposal with the first inspection, identify recoverable stock and obtain the plumbing report. Retain the email that supplied the revised proposal and distinguish its attachment from the earlier loose inspection.

Annotated photo exhibit

AV-26-004507 | Synthetic scenario photos; original JPGs retained separately

PHOTO EXHIBIT | AV-26-004507





A - Wall staining and local wetting

B - Moisture-affected cartons; value unverified

Synthetic photos. Annotations describe appearances, not cause, timing, liability or coverage.


How to read this exhibit

Marks A and B refer to visible appearances only. Compare the embedded images with the inspection narrative and the separate original JPGs. Not every visually useful detail is transcribed into the report text.

These are generated scenario images, not independently dated field photographs. A later image cannot prove an earlier event sequence or reveal concealed conditions.

Location and evidence sketch

AV-26-004507 | Embedded case-specific diagram - not to scale



Interpretation and unresolved evidence

The workshop sketch separates the reported north-wall area, wet stock and illustrated zone readings. The ingress route, machinery condition and stock valuation are unresolved.

The original inspection totals 48,600.00. A later PDF proposal adds 3,800.00 for controls and totals 52,400.00. The proposed addition has no supporting diagnostic report. The reserve of 68,000.00 is not a settlement or repair estimate.