

Thermal Survey Report

Property: 35 Lynton Road

Inspector: Michila, Philip

Survey Date: 2026-02-25

Executive Summary

1

TOTAL FINDINGS

0

CRITICAL ISSUES

0

HIGH PRIORITY

Detailed Findings

Finding 1: Heat loss at Wall #1

Severity: LOW | **Type:** Wall

Temperature: Max 2.0°C / Avg 2.0°C / Min 2.0°C

Heat loss detected at wall location. Temperature readings range from 2.0°C to 2.0°C, averaging 2.0°C. This is a minor heat loss point for consideration.



Recommendations

Wall #1 (HIGH priority)

- Inspect cavity insulation levels
- Consider external or internal wall insulation
- Check for thermal bridging at structural elements
- Investigate damp or missing insulation

Estimated savings: 15-35% on heating costs

Recommendations & Resources

Loading...

Your Survey Organisation

<https://example.com> | contact@example.com

Report generated on 2026-02-25 10:01