

Thermal Survey Report

Property: 35 Lynton Road

Inspector: Michila, Philip

Survey Date: 2026-02-26

Executive Summary

1

TOTAL FINDINGS

0

CRITICAL ISSUES

0

HIGH PRIORITY

Detailed Findings

Finding 1: Heat loss at Door #1

Severity: LOW | **Type:** Door

Temperature: Max 2.1°C / Avg 2.1°C / Min 2.1°C

Heat loss detected at door location. Temperature readings range from 2.1°C to 2.1°C, averaging 2.1°C. This is a minor heat loss point for consideration.



Recommendations

Door #1 (MEDIUM priority)

- Install or replace door sweep at bottom
- Add weather stripping to frame
- Consider thermal door curtain
- Check threshold and seal gaps

Estimated savings: 5-10% on heating costs

Documents & Links

- [Recommended notes](#)

Recommendations & Resources

Loading...

Your Survey Organisation

<https://example.com> | contact@example.com

Report generated on 2026-02-26 04:27