

Thermal Survey Report

Table of Contents

- [Cover Page](#)
- [Executive Summary](#)
- [Survey Findings](#)
- [Technical Survey Details](#)
- [Recommendations](#)

Cover Page

Property Address: 123 Main Street, Chesham

Survey Date: 2025-11-13

Inspector: Jon Andrew

Company Logo: [Logo placeholder]

Professional building inspection survey conducted using a FLIR infrared camera.

Executive Summary

The thermal inspection identified several minor and one significant anomaly. No major safety issues detected.

Statistic	Value
Number of findings	2
Highest anomaly severity	High
Survey duration	45 min

Survey Findings

Thermal bridge detected at window frame

Temperature differential around window frame suggests possible thermal bridge. Recommend insulation retrofit.

Max Temperature: 21.2°C

Min Temperature: 12.8°C

Severity: Medium

Thermal Image: [thermal image placeholder]

Visible Image: [visible image placeholder]

Heat loss at loft hatch

Elevated infrared readings at loft hatch indicate potential air leakage or poor insulation.

Max Temperature: 22.0°C

Min Temperature: 14.3°C

Severity: High

Thermal Image: [thermal image placeholder]

Visible Image: [visible image placeholder]

Technical Survey Details

Parameter	Value
Camera Model	FLIR E6
Resolution	160 x 120
Temperature Range	-20°C to 250°C
Survey Time	45 min
Ambient Temperature	13°C

Recommendations

- Improve insulation around window frames to eliminate thermal bridges.
- Seal and insulate loft hatch to reduce heat loss.

Page numbers, headers, and footers are present in the report template and will be auto-generated in actual use.