



SW/FW Release note 2022.12.05

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of DADman control software Product firmware. The released DADman is applicable for the products AX32, DX32, Penta and DAD Thunder|Core series, MOM, Avid MTRX and Avid MTRX Studio, generally denominated the Products in this document.

This new release covers only the Mainboard Firmware for AX32, DX32, Penta 720, Penta 721s and Avid MTRX. One bug is fixed related to reset of the 3G SDI I/O card during power up. Also there is now support for the new Dante Brooklyn 3 modules

DADman control software:	MacOS	No change
Compatible with Mac OS X 10.10/11 MacOS 10.12 to 10.15 and MacOS 11 and 12 with Intel or M1 processor	v.5.6.5 build 1	
Windows 7, 8, 10 and 11	Win v.5.6.5 build 1	No change
Thunder Core driver software:		
DAD Thunderbolt 3 Core Audio Driver:	v.1.1.9.4 beta	No change
Compatible with macOS 11/Big Sur and macOS 12/Monterey on Apple Silicon/M1 and Intel Computers		
Note this version is an internal release and still in beta		
Note. The ASIO Driver for Windows is not released		
Main board firmware for:		
AX32, DX32, Penta 720, Penta 721s, Avid MTRX	v.2.3.6.1	New
Brooklyn 2 Dante module (Dante version 4.0.9.1)	v.1.0.2.1	No change
Brooklyn 3 Dante module (Dante version 4.2.3.8)	v.1.1.0.2	New
Main board firmware for:		
MTRX Studio	v.1.1.1.5	No change
MTRX Studio Dante 64 IPCore (Dante version 1.3.7.1)	v.1.0.0.4	No change



New features

The main new features are:

- The firmware for AX32, DX32, Penta 720, Penta 721s and Avid MTRX now support the installation of the new Brooklyn 3 module. The firmware supports both the Brooklyn 2 and the Brooklyn 3 module, and any of the modules can be used.

Bug fixes

Correction in the firmware for AX32, DX32, Penta 720, Penta 721s and Avid MTRX.

- The card reset mechanism has been improved related to the 3GSDI I/O Card. Apparently some spread in component tolerances have revealed that the previous timing was marginal and could cause that sometimes the SDI channels would not be enabled correctly after power up.