



SW/FW Release note 2024.03.06.

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of the DADman control software and the updated firmware. The released functionality is applicable for the products AX32, DX32, Penta and DAD Thunder|Core series, MOM, Avid MTRX, Avid MTRX Studio and Avid MTRX II, generally denominated the Products in this document.

This new release covers support for DADlink in the firmware for AX32, DX32, Penta and Avid MTRX. The firmware for the ThundeCore products and MTRX II now have an updated DADlink functionality that is compatible with AX32, DX32, Penta and Avid MTRX.

DADman now supports DADlink on all the products listed above. New functionality has been added so the application can run in the menu bar only, the mode of the talkback function is extended, as well as other various new features have been added.

For a description of the DADlink functionality reference is made to the document: *Technical note, DADlink and Mini MADI module*.

DADman control software:	MacOS	No change
Compatible with MacOS 10.13 to 10.15 and MacOS 11, 12, 13 and 14 with Intel or Apple silicon processor	v.5.7.0 build 1	
Windows 10 and 11	Windows	No change
	v.5.7.0 build 1	
Thunder Core driver software:	MacOS	No change
DAD Thunderbolt 3 Core Audio Driver:	v.1.1.26	
Compatible with macOS 11, 12, 13 and 14 Apple Silicon and Intel Computers		
DAD Thunderbolt 3 Windows ASIO driver	Windows	No change
Compatible with Windows 10 and 11	v. 1.1.2	
Main board firmware for:		
AX32, DX32, Penta 720, Penta 721s, Avid MTRX	v.2.4.2.2	New
Brooklyn 2 Dante module (Dante version 4.0.9.1)	v.1.0.2.1	No change
Brooklyn 3 Dante module (Dante version 4.2.3.8)	v.1.1.0.2	No change



Main board firmware for:

MTRX Studio	v.1.1.3.1	No change
MTRX Studio Dante 64 IPCore (Dante version 1.3.7.1)	v.1.0.0.4	No change

Main board firmware for:

AX64, AX Center, Core256 and Avid MTRX II	v.1.0.5.2	No change
Dante 256 IPCore (Dante version 4.1.1.1)	v.1.0.2.1	No change

New features, firmware

No new features

New features, DADman

No new features.

Bug fixes

Fixes in Mainboard firmware

Mainboard firmware for AX32, DX32, Penta 720, Penta 721s, Avid MTRX: A timing and format error in the DigiLink interface has been corrected. The change is only relevant for MTRX. In the previous firmware version 2.4.1.2 a bug on the DigiLink interface occurred. The bug is not in the earlier versions. This is corrected in the new version.