



SW/FW Release note 2025.01.09

Introduction.

This document gives a short description of the new functions, features and bug fixes introduced in this release of the DADman control software and the updated firmware. The released functionality is applicable for the products AX32, DX32, Penta and DAD Thunder | Core series, MOM, Avid MTRX, Avid MTRX Studio, Avid MTRX II and Dynaudio Control 01, generally denominated the Products in this document.

This new release only addresses the firmware for the Thunder | Core products and in particular AX Center and the Dante Card where a bug had been fixed.

The details are listed below.

DADman control software:	MacOS	No change
Compatible with MacOS 10.13 to 10.15 and MacOS 11, 12, 13, 14 and 15 with Intel or Apple silicon processor	v.5.8.0 build 8	
Please see note below on MacOS 15 compatibility		No change
Windows 10 and 11	Windows v.5.8.0 build 8	
Thunder Core driver software:	MacOS	No change
DAD Thunderbolt 3 Core Audio Driver:	v.1.2.2	
Compatible with macOS 11, 12, 13, 14 and 15 Apple Silicon and Intel Computers		
DAD Thunderbolt 3 Windows ASIO driver	Windows v. 1.1.2	No change
Compatible with Windows 10 and 11		
Main board firmware for:		
AX64, AX Center, Core256, Avid MTRX II and Control 01	v.1.1.0.4	New
Dante 256 IPCore (Dante version 4.1.1.1)	v.1.0.2.1	No change

Main board firmware for:



AX32, DX32, Penta 720, Penta 721s, Avid MTRX	v.2.4.4.1	No change
Brooklyn 2 Dante module (Dante version 4.0.9.1)	v.1.0.2.1	No change
Brooklyn 3 Dante module (Dante version 4.2.3.8)	v.1.1.0.2	No change
Main board firmware for:		
MTRX Studio	v.1.1.5.1	No change
MTRX Studio Dante 64 IPCore (Dante version 1.3.7.1)	v.1.0.0.4	No change

New in the firmware

Native functionality for Thunder Core products – Bug Fix

- All Thunder Core products as well as MTRX II and Control 01 run with the same generic firmware. In this new release two bug has been fixed, one with relation to the two-channel analogue input section on the AX Center and one for the optional 128 ch. Dante Card.
- In some cases, the ADC chipset would not pass audio, due to a timing error in the design. This is fixed in the new release of the firmware.
- When selecting external synchronization to the Dante network on the 128ch. Dante Card, the selection DADman did not setup the card correctly. This has been fixed.