


8 entrega

$2^n = 16$

A	B	C	D	S	S'
0	0	0	0	0	0
0	0	0	1	0	0
0	0	1	0	0	0
0	0	1	1	0	0
0	1	0	0	0	0
0	1	0	1	0	0
0	1	1	0	0	0
0	1	1	1	0	0
1	0	0	0	0	0
1	0	0	1	0	0
1	0	1	0	0	0
1	0	1	1	0	0
1	1	0	0	0	0
1	1	0	1	0	0
1	1	1	0	0	0
1	1	1	1	1	0


(giro) sensor de rotación = A
 (posición) detector de contacto = B
 (retro. sig. iz.) nivel de depósito = C
 (mecaniz. pasado) indicador de mecanización = D
 S = abrir electroválvula
 S' = emergencia
 1 = libre/normal
 0 =

$$S = ABC\bar{D} + ABCD$$




AB/CD	$\bar{C}\bar{D}$	$\bar{C}D$	CD	$C\bar{D}$
$\bar{A}\bar{B}$	00	00	00	00
$\bar{A}B$	01	00	00	01
AB	11	00	11	10
$A\bar{B}$	10	00	00	00

$$S = ABC$$



$$S' = \bar{A}\bar{B}\bar{C}D + AB\bar{C}D$$



AB/CD	$\bar{C}\bar{D}$	$\bar{C}D$	CD	$C\bar{D}$
$\bar{A}\bar{B}$	00	00	00	00
$\bar{A}B$	01	01	00	00
AB	11	01	10	00
$A\bar{B}$	10	00	00	00

$$S = B\bar{C}D$$

