

REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

Fill the Information Belo	ow							
Company: Rezayat Company Limited						Date: 28-01-2021		
Location: Area 1					Time: 10:00 AM			
Project/ Site Name: Catering	. Audit	orium & Recreation Facilities	: 097	-C76R				
Person(s) Involved:		Employee		Contractor		Others		
		1 3	3.					
1. Ichara Malik (30038958)			3.					
2.			Oth	ner(s).				
Type of Incident:								
Fatality	$\overline{}$	Lost Time Injury		Dangerous Occurrence		First Aid	$\overline{\top}$	
Injury Location by Body	Parts	S (Select one or more if necessa	ıry):					
Head		Chest		Hand		Eyes		
Face		Leg		Arm		Hip		
Neck		Abdomen		Wrist		Ankle/Foot		
Back		Stomach		Elbow		Knee		
Nose/ Ears		Shoulder		Fingers/ Thumb		Toes		
Type of Injury Sustained	l (Sele	ct one or more if necessary):						
Fracture	$\overline{}$	Cut/ Laceration		Scalping		Bruising	$\overline{}$	
Loss of Sight		Loss of Consciousness		Heat		Amputation		
Dislocation		Crush Injury		Cold		Other(s) (Near miss)	✓	
Abrasion		Suffocation		Burn				
Immediate Cause(s) (Sel	ect one	or more if necessary):						
Safety Rule Violated	✓	Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility	$\overline{}$	
Lack of Task Skill		Method Deviation		Poor Housekeeping		Employee Morale		
Lack of Supervision	✓	Poor Weather Conditions		Inadequate Lighting		Employee Attitude		
Improper Lifting (MH)		Lack of Task Knowledge		Poor Team Work		Behavior Problem		
Not Paying Attention		Lack of Communication		No Risk Assessment		Poor Ground Conditions		
Human Error	✓	Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)		
Inadequate PPE		Defective Tools		Unprotected excavation		Unprotected Edge		
Animals		Violence		Horseplay		Improper/ Poor Slinging		
Heat Stress	\bot	STF Above Ground		STF on the Same Level		Manual Handling	_	
Misuse of Hand Tools	+	Grinding/ Welding		Knives/ Sharps		Hit by Vehicle	_	
Hit by Static Machinery Stress		Heavy Equipment Fatigue		Splashes from C.P.O.L. Vandalism	-	Other(s)	-	
Equipment(s) Involved:		raugue		vanuansin				
* * * * * * * * * * * * * * * * * * * *			1		1			
Light Vehicle:	\bot	Heavy Vehicle:		Plant Equipment:	 	Static Plant Equipment:	_	
Building:		Structure:		Scaffold:	✓	Excavation:	_	
Other(s):								
Description of the Event	:							
While removing the sh	utteri	ng of the column in par	t 2, s	teel rod that was given a	s a s	upport on the shuttering	(as	
•				s not barricaded and no		•	`	
• • •	511 011	to the ground. The area	a wa.	3 not barricaded and no t	JIIC V	vas present downside to		
monitor.								
		aterial damage was obs						
Immediate Action(s) Ta	ken to	o Prevent Reoccurance (I	f Any	') :				
 Work was stopped 	and I	ncident was investigated.						
 Before removing the 	าe shu	ttering, tie the supporting roo	d with	binding wires to avoid falling.				
 Barricade the area 	from (downside.						
 Always depute one 	e perso	on downside to monitor pede	estriar	access.				
 Provide overhead 	pedes	trian crossing shed to avoid	falling	materials on the pedestrians.				
Person Created the Repo	ort:							
Name: Waqas Gillani		Position: Safety Engineer		Signature: Krishna 🧸 💆	Y	Date: 28/01/2021		
1		1		-		İ		


Note: This form is to be submitted four (4) hours after the incident occurred.



REZAYAT GROUP Health and Safety



Initial Incident/Accident Report





REZAYAT GROUP Health and Safety



Initial Incident/Accident Report



