Ref: RCL-HSE-FM-07.1

Version: 1.2

INITIAL ACCIDENT AND INCIDENT NOTIFICATION REPORT



Rev. Date: June 28, 2021

Fill the Information	Below						
Company: Rezayat company limited					Date: 16/07/2022		
Location: Yanbu					Time: 5.30pm		
Project/ Site Name: PIC F 8194 Construction of public housing				Worst Potential Severity: 2			
Person(s) Involved:	Employee	1	Contractor	Act	ual Severity: 4 Others		
			Contractor		Others		
1. Mohammad l	Nur B#30040805	3.					
2.		Oth	er(s).				
Type of Incident:							
Ill Health							
	ody Parts (Select one or more if	necessary):					
Head	Chest		Hand	V	Eyes		
Face	Leg		Arm	^	Hip		
Neck	Abdomen		Wrist		Ankle/Foot		
Back	Stomach		Elbow		Knee		
Nose/ Ears	Shoulder		Fingers/ Thumb		Toes		
	ined (Select one or more if necess	sary):	J/				
Fracture	Cut/ Laceration		Scalping		Bruising	X	
Loss of Sight	Loss of Consciousness		Heat		Amputation	23	
Dislocation	Crush Injury		Cold		Other(s)		
Abrasion	Suffocation		Burn				
Immediate Cause(s)	(Select one or more if necessary):	,					
Safety Rule Violated	Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility		
Lack of Task Skill	Method Deviation	X	Poor Housekeeping		Employee Morale		
Lack of Supervision	Poor Weather Conditio	ns	Inadequate Lighting		Employee Attitude		
Improper Lifting (MH)	Lack of Task Knowledg		Poor Team Work		Behavior Problem		
Not Paying Attention	Lack of Communication	1	No Risk Assessment		Poor Ground Conditions		
Human Error	Incorrect Tools/Equip		Defective Equipment	X			
Inadequate PPE	Defective Tools Violence		Unprotected excavation Horseplay		Unprotected Edge Improper/ Poor Slinging		
Animals Heat Stress	STF Above Ground		STF on the Same Level		Manual Handling		
Misuse of Hand Tools	Grinding/ Welding		Knives/ Sharps		Hit by Vehicle		
Hit by Static Machinery	Heavy Equipment		Splashes from C.P.O.L.		Other(s):		
Stress	Fatigue		Vandalism				
Equipment(s) Involv	ved:						
Light Vehicle:	Heavy Vehicle:		Plant Equipment:	Y	Static Plant Equipment:		
Building:	Structure:		Scaffold:	Λ	Excavation:		
Other(s):							
Description of the Ev	vent:						
(Jumping compa power source wit	-Helper got light bruise i ctor) by the incorrect metl h damagedcable by touchi Taken to Prevent Reoccur	hod advise ing the equ	d by mechanic person aipment body which is	nel whe	ere he tries to disconnec		
	nt has been stopped and R			fix the d	amage switch		
Person Created the I	Report:						
Person Created the I	Daritian During HCI		Signature:		Date: 2022-07- 16		


Ref: RCL-HSE-FM-07.1

Version: 1.2

INITIAL ACCIDENT AND INCIDENT NOTIFICATION REPORT



Rev. Date: June 28, 2021



Note: please indicate by using an X in the box next to the injured part/parts, this should match the injury description above.

Name:	Signatura
Name:	Signature: