Ref:

RCL-HSE-FM-07.4

Version:

1.2

Rev. Date: June 28, 2021

INITIAL ACCIDENT AND INCIDENT NOTIFICATION REPORT



Fill the Information Below							
Company: RCL				Da	Date: 5/17/2022		
Location: Jubail				Ti	Time: 8:40 AM		
Project/ Site Name: Berri				Worst Potential Severity: 3 Actual Severity: 3			
Person(s) Involved:	Employee		Contractor	8	Others	1963	
1. Shiva Bahadur Nepali — 3	6447	3.					
2.		Ot	her(s).				
Type of Incident:							
MTC							
Injury Location by Body Parts (Select one or more if necessary):							
Head	Chest		Hand		Eyes	T	
Face	Leg		Arm		Hip		
Neck	Abdomen		Wrist	1	Ankle/Foot		
Back	Stomach		Elbow		Knee		
Nose/ Ears	Shoulder		Fingers/Thumb		Toes		
Type of Injury Sustained (Select one or more if necessary):							
Fracture	Cut/ Laceration	1	Scalping	ALC: NO.	Bruising	1	
Loss of Sight	Loss of Consciousness		Heat	1	Amputation		
Dislocation	Crush Injury		Cold	0	Other(s)		
Abrasion	Suffocation		Burn				
Immediate Cause(s) (Select one or more if necessary):							
Safety Rule Violated	Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility		
Lack of Task Skill ✓	Method Deviation		Poor Housekeeping		Employee Morale		
Lack of Supervision ✓	Poor Weather Conditions		Inadequate Lighting		Employee Attitude		
Improper Lifting (MH)	Lack of Task Knowledge	V	Poor Team Work		Behavior Problem		
Not Paying Attention	Lack of Communication		No Risk Assessment		Poor Ground Conditions		
Human Error	Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)		
Inadequate PPE	Defective Tools		Unprotected excavation		Unprotected Edge		
Animals	Violence	-	Horseplay		Improper/ Poor Slinging	1	
Heat Stress	STF Above Ground	-	STF on the Same Level	-	Manual Handling	-	
Misuse of Hand Tools	Grinding/Welding		Knives/ Sharps	-	Hit by Vehicle	-	
Hit by Static Machinery Stress	Heavy Equipment	+	Splashes from C.P.O.L.	-	Other(s):	-	
	Fatigue		Vandalism		PROVINCE STORAGE STORAGE		
Equipment(s) Involved:							
Light Vehicle:	Heavy Vehicle:		Plant Equipment:		Static Plant Equipment:		
Building:	Structure:		Scaffold:		Excavation:		
Other(s): Power Tool							
(Jackhammer)		O Annual Property of the Parket		Sol			
Description of the Event:							

During the demolition work in 470 area inside the building, a worker was doing the wall chipping by a jackhammer (HILTI), While the worker was drilling the wall by positioning the HILTI vertically to upside direction, a piece of marble stone fell down and hit on his arm wrist by the sharp edge of the marble.

Immediate Action(s) Taken to Prevent Reoccurrence (If Any):

- Stop the work immediately
- Instructed the site foreman to do the manual chipping and not to use the HILTI for the same activity until finalize the investigation.
- Conducted the TBT and shared the lesson learning points with rest of the crew.

Position: Safety Lead

Advised the site foreman to provide the proper guidance and closely monitor the activity.

Person Created the Report:

Name: Abdul Sarbas

\(\lambda\)

Signature:

/

Date: 2022-05-19

Ref:

RCL-HSE-FM-07.4


Version:

1.2

Rev. Date: June 28, 2021

INITIAL ACCIDENT AND INCIDENT NOTIFICATION REPORT





Note: please indicate by using an X in the box next to the injured part/parts, this should match the injury description above.

Name: Shiva Bahadus Nepali

Signature: