

## **REZAYAT GROUP Health and Safety**



Initial Incident/Accident Report

Fill the Information Below							
Company: Rezayat Cmpany Limited				Dat	Date: 12/30/2021		
Location: Al Ula				Time:			
Project/ Site Name: Quran Charity Hotel Façade design and build				Worst Potential Severity: 2 Actual Severity: 2			
Person(s) Involved:	Employee		Contractor		Others		
1. Mokter Hossain-30040364		3					
2. Santosh Kumar Sharma-3003	7594	Otł	ner(s).				
Type of Incident:							
First Aid Case							
Injury Location by Body Par	ts (Select one or more if necessa	rv):					
		ıyı.			1		
Head	Chest		Hand		Eyes		
Face	Leg		Arm		Hip		
Neck Page	Abdomen		Wrist	X	Ankle/Foot		
Back Naga / Fare	Stomach		Elbow		Knee		
Nose/ Ears	Shoulder		Fingers/ Thumb		Toes		
Type of Injury Sustained (Se	lect one or more if necessary):						
Fracture	Cut/ Laceration	X	Scalping		Bruising		
Loss of Sight	Loss of Consciousness		Heat		Amputation		
Dislocation	Crush Injury		Cold		Other(s)		
Abrasion	Suffocation		Burn		Swelling		
Immediate Cause(s) (Select one or more if necessary):							
Safety Rule Violated	Lack of Resources		Drugs/ Alcohol Related	1	Inadequate Visibility		
Lack of Task Skill	Method Deviation		Poor Housekeeping		Employee Morale		
Lack of Supervision	Poor Weather Conditions		Inadequate Lighting		Employee Attitude		
Improper Lifting (MH)	Lack of Task Knowledge		Poor Team Work		Behavior Problem		
Not Paying Attention			No Risk Assessment		Poor Ground Conditions		
Human Error	Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)		
Inadequate PPE	Defective Tools		Unprotected excavation		Unprotected Edge		
Animals	Violence		Horseplay		Improper/ Poor Slinging		
Heat Stress	STF Above Ground		STF on the Same Level		Manual Handling		
Misuse of Hand Tools	Grinding/ Welding		Knives/ Sharps	X	Hit by Vehicle		
Hit by Static Machinery	Heavy Equipment		Splashes from C.P.O.L.		Other(s):		
Stress	Fatigue		Vandalism				
Equipment(s) Involved:							
Light Vehicle:	Heavy Vehicle:	X	Plant Equipment:		Static Plant Equipment:		
Building:	Structure:	Λ	Scaffold:	1	Excavation:		
Other(s):			Scanoiu.	1	Excavation.		
Description of the Event:	1 Tott duling Tebai						
Description of the Event:							
On 30 Dec around 10.25pm, It has been reported by Mr.Moketer Hossain –carpenter B#30040364 that during form work preparation, he got small cut on his left hand wrist by the protruding rebar placed inside the form work. Immediately first aid treatment has been given at Site office.							
Immediate Action(s) Taken to Ducyant Decommence (If Ann)							
Immediate Action(s) Taken to Prevent Reoccurrence (If Any):							
<ul> <li>Reported to Steel fixing Forman to place safety cover once the steel placed</li> <li>Advised the victim to identify the hazards in the workplace before start</li> </ul>							
Person Created the Report:							
			Signatura				
Name: Rejenson Fernando	Position: Safety Lead		Signature:		Date: 12/30/2021		

Note: This form is to be submitted four (4) hours after the incident occurred.



## **REZAYAT GROUP Health and Safety**









