

REZAYAT GROUP Health and Safety



Initial Incident/Accident Report

Fill the Information Below								
Company: Rezayat Cmpany Limited						Date: 10/29/2021		
Location: Al Ula					Tir	Time:		
Project / Site Name: Ouran Charity Hotel Facade design and huild						orst Potential Severity: 5 tual Severity: 1		
Person(s) Involved:	X	Employee		Contractor		Others		
1. Shazaman B# 30037123			3					
2. Balwant Rai B#30039038			Otr	ier(s).				
Type of Incident:								
RTA								
Injury Location by Body P	art	S (Select one or more if necessar	ry):					
Head		Chest		Hand		Eyes		
Face		Leg		Arm		Hip		
Neck		Abdomen		Wrist		Ankle/Foot		
Back		Stomach		Elbow		Knee		
Nose/ Ears		Shoulder		Fingers/ Thumb		Toes		
Type of Injury Sustained (Select one or more if necessary):								
Fracture		Cut/ Laceration		Scalping		Bruising		
Loss of Sight		Loss of Consciousness		Heat		Amputation		
Dislocation		Crush Injury		Cold		Other(s)		
Abrasion		Suffocation		Burn		Swelling		
Immediate Cause(s) (Select one or more if necessary):								
Safety Rule Violated		Lack of Resources		Drugs/ Alcohol Related		Inadequate Visibility		
Lack of Task Skill		Method Deviation		Poor Housekeeping		Employee Morale		
Lack of Supervision	X	Poor Weather Conditions		Inadequate Lighting		Employee Attitude		
Improper Lifting (MH)		Lack of Task Knowledge		Poor Team Work		Behavior Problem		
Not Paying Attention	X	Lack of Communication		No Risk Assessment		Poor Ground Conditions		
Human Error		Incorrect Tools/Equip		Defective Equipment		Improper Lifting (crane)		
Inadequate PPE		Defective Tools		Unprotected excavation		Unprotected Edge		
Animals		Violence		Horseplay		Improper/ Poor Slinging		
Heat Stress		STF Above Ground		STF on the Same Level		Manual Handling		
Misuse of Hand Tools		Grinding/ Welding		Knives/ Sharps		Hit by Vehicle		
Hit by Static Machinery		Heavy Equipment		Splashes from C.P.O.L.		Other(s):		
Stress		Fatigue		Vandalism				
Equipment(s) Involved:								
Light Vehicle:		Heavy Vehicle:	X	Plant Equipment:		Static Plant Equipment:		
Building:		Structure:		Scaffold:		Excavation:		
Other(s):								
Description of the Event:								
-								
On 20 Oct around 2 20nm	1+ k	as been reported by Dyna	dri	vor Mr Shazaman that	t hath tha	tires on rear left side of ve	hiclo	
On 29 Oct around 3.30pm, It has been reported by Dyna driver Mr.Shazaman that both the tires on rear left side of vehicle								
# 7402 VHA were burst out in the middle of road during the travel from Yanbu to Al ula. This happens due to heavy load on								
left side of the vehicle as p	er (driver and Auto workshop	Fησ	ineer				
iere side of the vernere as p	<i>.</i>	anver una riato wontonop	6	incer.				
Immediate Action(a) Taken to Drayant Decompress (If Ann).								
Immediate Action(s) Taken to Prevent Reoccurrence (If Any):								
Reported to Auto workshop Engineer for replacement of tires.								
Advised the driver to place warning triangles								
	1							
Person Created the Report:								
		B. W. C.S		Signature:	~	D		
Name: Rejenson Fernando		Position: Safety Lead		Signature:		Date: 10/30/2021		

Note: This form is to be submitted four (4) hours after the incident occurred.



REZAYAT GROUP Health and Safety



Initial Incident/Accident Report







