Engineer's Inspection Report
Office of the State Engineer
Dam Safety Program

COLORADO
Division of Water Resources
Department of Natural Resources

Inspector: Gavin, Matthew

Dam Name: TURNER	T: 36N R: 9W S: 21	County: LA PLATA	Date of Inspection: 04/28/2026
Dam ID: 300113 Year Completion: 1969	Dam Height (ft): 35.0	Spillway Width (ft): 125.0	Previous Inspection: 05/02/2025
Hazard Class: High	Dam Length (ft): 510.0	Spillway Capacity (cfs): 5,000.0	Normal Storage (af): 472.0
Division: 7 Water District: 30	Crest Width (ft): 22.0	Freeboard (ft): 6.0	Surface Area (ac): 42.0
EAP: 10/01/2022	Crest Elevation (ft): 7,150.0	Drainage Area (ac): 4,057.0	Outlet Inspected: 05/02/2025

Current Restriction: -- None --

Owner:	FALLS CREEK RANCH ASSOCIATION, INC. (SOUTHWORTH, S	Owner Representation:	SOUTHWORTH, SCOTT
Address:	6350 FALLS CREEK MAIN	Contact Name:	SCOTT SOUTHWORTH
	DURANGO CO 81301-0000	Contact Phone:	(970) 247-9506X

Inspection Party:	Scott Southworth	James Glover
Representing:	Falls Creek Ranch Assoc.	Falls Creek Ranch Assoc.

Field Condition Observed

Water Level: Below Dam Crest 6 Ft. FT. Above Spillway: 0.1 FT. Gage Rod Reading:

Ground Moisture Condition: ☐ Dry ☐ Wet ☐ Snowcover

General Field Observations (Weather, Recent, Precipitation Events, Etc.)

Reservoir level was right at spillway crest with standing water in channel. Most flow conveyed through diversion.

Directions: Mark a ✓ for conditions found and underline words that apply

Upstream Slope

Problems Noted: ☑ (0) None ☐ (1) Riprap - Missing, Sparse, Displaced, Weathered ☐ (2) Wave Erosion - With Scarps ☐ (3) Cracks with Displacement ☐ (4) Sinkhole ☐ (5) Appears too Steep ☐ (6) Depression or Bulges ☐ (7) Slides ☐ (8) Concrete Facing - Holes, Cracks, Displaced, Undermined ☐ (9) Other

Vegetation is well-controlled. No concerns noted.

Conditions Observed: ◉ Good ○ Acceptable ○ Poor

Crest

Problems Noted: ☑ (10) None ☐ (11) Ruts or Puddles ☐ (12) Erosion ☐ (13) Cracks - with Displacement ☐ (14) Sinkholes ☐ (15) Not Wide Enough ☐ (16) Low Area ☐ (17) Misalignment ☐ (18) Improper Surface Drainage ☐ (19) Other

Well-maintained. Good vegetative cover - mostly grass.

Conditions Observed: ◉ Good ○ Acceptable ○ Poor

Engineer's Inspection Report

Dam Name: TURNER **Dam ID:** 300113 **Inspector:** Gavin, Matthew **Date of Inspection:** 04/28/2026

Downstream Slope

Problems Noted: ☑ (20) None ☐ (21) Livestock Damage ☐ (22) Erosion or Gullies ☐ (23) Cracks - with Displacement ☐ (24) Sinkholes ☐ (25) Appear Too Steep ☐ (26) Depression or Bulges ☐ (27) Slide ☐ (28) Soft Area ☐ (29) Other

Fairly uniform with decent vegetative cover. No immediate concerns.

Conditions Observed: ○ Good ◉ Acceptable ○ Poor

Seepage

Problems Noted: ☑ (30) None ☐ (31) Saturated Embankment Area ☐ (32) Seepage Exits on Embankment ☐ (33) Seepage Exits at Point Source ☐ (34) Seepage Area at Toe ☐ (35) Flow Adjacent to Outlet ☐ (36) Seepage Increased/Muddy

Drain Outfalls Observed: ☐ No ☑ Yes (show location of drains on sketch and indicate amount and quality of discharge) ☐ (37) Flow Increased/Muddy ☐ (38) Drain Dry/Obstructed ☐ (39) Other

Dam exhibits very good seepage control. No signs of seepage observed.

Conditions Observed: ◉ Good ○ Acceptable ○ Poor

Outlet

Problems Noted: ☐ (40) None ☐ (41) No Outlet Found ☐ (42) Poor Operating Access ☐ (43) Inoperable ☐ (44) Upstream or Downstream Structure Deteriorated ☑ (45) Outlet Operated During Inspection

Interior Inspected: ☐ Yes ☑ No ☐ (46) Conduit Deteriorated or Collapsed ☐ (47) Joint Displaced ☑ (48) Value Leakage ☐ (49) Other

Outlet lined with felt-style CIPP in 2013. 20-10C gate exhibits minor leakage. (45) Outlet exercised without incident.

Conditions Observed: ○ Good ◉ Acceptable ○ Poor

Spillway

Problems Noted: ☑ (50) None ☐ (51) No Emergency Spillway Found ☐ (52) Erosion with Backcutting ☐ (53) Crack - with Displacement ☐ (54) Appears to be Structurally Inadequate ☐ (55) Appears too Small ☐ (56) Inadequate Freeboard ☐ (57) Flow Obstructed ☐ (58) Concrete Deteriorated / Undermined ☐ (59) Other

No changes or concerns noted.

Conditions Observed: ◉ Good ○ Acceptable ○ Poor

Engineer's Inspection Report

Dam Name: TURNER **Dam ID:** 300113 **Inspector:** Gavin, Matthew **Date of Inspection:** 04/28/2026

Monitoring

Existing Instrumentation Found: ☐ (110) None ☑ (111) Gage Rod ☐ (112) Piezometers ☐ (113) Seepage Weirs/Flumes ☑ (114) Survey Monuments ☐ (115) Other

Monitoring of Instrumentation: ☐ (116) No ☑ (117) Yes

Periodic Inspection By: ☑ (118) Owner ☐ (119) Engineer

Dam is in highly visible location with engaged residents and Owners Group.

Conditions Observed: ○ Good ◉ Acceptable ○ Poor

Maintenance and Repairs

Problems Noted: ☑ (60) None ☐ (61) Access Road Needs Maintenance ☐ (62) Livestock Damage ☐ (63) Brush on Upstream Slope, Crest, Downstream Slope, Toe ☐ (64) Trees on Upstream Slope, Crest, Downstream Slope, Toe ☐ (65) Rodent Activity on Upstream Slope, Crest, Downstream Slope, Toe ☐ (66) Deteriorated Concrete Facing, Outlet, Spillway ☐ (67) Gate and Operating Mechanism Need Maintenance ☐ (68) Other

Well-maintained dam.

Conditions Observed: ◉ Good ○ Acceptable ○ Poor

Overall Conditions

Dam continues to perform as expected and is well-maintained.

Based on this Safety Inspection and recent file review, the overall condition is determined to be:

◉ (71) Satisfactory ○ (72) Conditionally Satisfactory ○ (73) Unsatisfactory

Items Requiring Action by Owner to Improve the Safety of the Dam

The State Engineer, by providing this dam safety inspection report, does not assume responsibility for an unsafe condition of the subject dam. The sole responsibility for the safety of this dam rests with the reservoir owner or operator, who should take every step necessary to prevent damages caused by leakage or overflow of waters from the reservoir or floods resulting from a failure of the dam.

Engineer's Inspection Report

Dam Name: TURNER **Dam ID:** 300113 **Inspector:** Gavin, Matthew **Date of Inspection:** 04/28/2026

Safe Storage Level: Recommended as a Result of this Inspection

- [x] (101) Full Storage
- [ ] (102) Conditional Full Storage
- [ ] (103) Recommended Restriction
- [ ] (104) Continue Existing Restriction

→

FT. Below Dam Crest

FT. Below Spillway Crest

FT. Gage Height

☐ No Storage - Maintain Outlet Fully Open

Reason for Restriction:

Actions Required for Conditional Full Storage or Continued Storage at the Restricted Level:

Engineer's Signature: Matthew J Gavin — Digitally signed by Matthew J Gavin Date: 2026.05.11 13:47:12 -06'00'

Inspected By

Owner's Signature: _____

Owner/Owner's Representative

Date: ____/____/____

Engineer's Inspection Report

Dam Name: TURNER **Dam ID:** 300113 **Inspector:** Gavin, Matthew **Date of Inspection:** 04/28/2026

Guidelines for Determining Conditions

Conditions Observed - Applies to Upstream Slope, Crest, Downstream Slope, Outlet, Spillway

Good
In general, this part of the structure has a near new appearance, and conditions observed in this area do not appear to threaten the safety of the dam.

Acceptable
Although general cross-section is maintained, surfaces may be irregular, eroded, rutted, spalled, or otherwise not in new condition. Conditions in this area do not currently appear to threaten the safety of the dam.

Poor
Conditions observed in this area appear to threaten the safety of the dam.

Conditions Observed - Applies to Seepage

Good
No evidence of uncontrolled seepage. No unexplained increase in flows from designed drains. All seepage is clear. Seepage conditions do not appear to threaten the safety of the dam.

Acceptable
Some seepage exists at areas other than the drain outfalls, or other designed drains. No explained increase in seepage. All seepage is clear. Seepage conditions observed do not currently appear to threaten the safety of the dam.

Poor
Seepage conditions observed appear to threaten the safety of the dam. Examples: 1) Designed drain or seepage flows have increased without increase in reservoir level. 2) Drain or seepage flows contain sediment, i.e., muddy water or particles in jar samples. 3) Widespread seepage, concentrated seepage, or ponding appears to threaten the safety of the dam.

Conditions Observed - Applies to Monitoring

Good
Monitoring includes movement surveys and leakage measurements for all dams, and piezometer readings for High hazard dams. Instrumentation is in reliable, working condition. A plan for monitoring the instrumentation and analyzing results by the owner's engineer is in effect. Periodic inspections by owner's engineer.

Acceptable
Monitoring includes movement surveys and leakage measurements for High and Significant hazard dams; leakage measurements for Low hazard dams. Instrumentation is in serviceable condition. A plan for monitoring instrumentation is in effect by owner. Periodic inspections by owner or representative. Or, No Monitoring Required.

Poor
All instrumentation and monitoring described under "ACCEPTABLE" here for each class of dam, are not provided, or required periodic readings are not being made, or unexplained changes in readings are not reacted to by the owner.

Conditions Observed - Applies to Maintenance and Repair

Good
Dam appears to receive effective on-going maintenance and repair, and only a few minor items may need to be addressed.

Acceptable
Dam appears to receive maintenance, but some maintenance items need to be addressed. No major repairs required.

Poor
Dam does not appear to receive adequate maintenance. One or more items needing maintenance or repair has begun to threaten the safety of the dam.

Overall Conditions

Satisfactory
The safety inspection indicates no conditions that appear to threaten the safety of the dam, and the dam is expected to perform satisfactorily under all design loading conditions. Most of the required monitoring is being performed.

Conditionally Satisfactory
The safety inspection indicates symptoms of structural distress (seepage, evidence of minor displacements, etc.)

Unsatisfactory
The safety inspection indicates definite signs of structural distress (excessive seepage, cracks, slides, sinkholes, severe deterioration, etc.), which could lead to the failure of the dam if the reservoir is used to full capacity. The dam is judged unsafe for full storage of water.

Safe Storage Level

Full Storage
Dam may be used to full capacity with no conditions attached.

Conditional Full Storage
Dam may be used to full storage if certain monitoring, maintenance, or operational conditions are met.

Restriction
Dam may not be used to full capacity, but must be operated at some reduced level in the interest of public safety.

Hazard Classification of Dams

High Hazard
Loss of human life is expected in the event of failure of the dam, while the reservoir is at the high water line.

Significant Hazard
Significant damage to improved property is expected in the event of failure of the dam while the reservoir is at the high water line, but no loss of human life is expected.

Low Hazard
Loss of human life is not expected, and damage to improved property is expected to be small, in the event of failure of the dam while the reservoir is at the high water line.

NPH hazard
No loss of life, or damage to improved property, or loss of downstream resource is expected in the event of failure of the dam while the reservoir is at the high water line.

PROJECT INFORMATION			
Dam Name:	Turner Dam	Inspector:	MJG
DAMID:	300113	Date:	04.28.2026

PICTURES



1. Looking Upstream in Spillway Channel



2. Downstream Slope from Right Side

PICTURES



3. Diversion Vault in Spillway Channel



4. Diversion Head Gate

PICTURES



5. Crest from Right End



6. Outlet Operator

PICTURES



7. Crest from Left End



8. Outlet Outfall

PICTURES



9. Exercising Outlet