

Column sources

Inverting outputs VCC turns source off

0V turns source on

10k input resistor built in

This v3 corrects:

2580 9 - 10 pin swap 4x

C8 C9 connection pin swap

Column sinks

VCC turns sink on

 $0V \; turns \; sink \; off \;$

10k input resistor built in

TITLE: REV: 1.0 Luminator Mark IV Slave Display Driver Board Sheet 2 Company: John Wolfe Sheet: 2/2 SeasyED# 2024-03-18 Drawn By: jpwole31