Project 2 | Board interface



NC E-stop: separate hardwired power-cut circuit. Feedback pin is not yet assigned.

Pin labels transcribed from the supplied sketch. Connector order and input polarity require confirmation.

Do not connect the tower relay supply or a 5V sensor output directly to an ESP32 GPIO.