


STM32F401RCT6.ino



/* Stepper Motor Control - one step at a time, drives a unipolar or bipolar stepper motor. The motor is attached to digital pins x x x x

The motor will step one step at a time, very slowly. You can use this to

The motor will step one step at a time, very slowly. You can use this to test that you've got the four wires of your stepper wired to the correct pins. If wired correctly, all steps should be in the same direction.

Use this also to count the number of steps per revolution of your motor, if you don't know it. Then plug that number into the oneRevolution example */

#include <Arduino.h> #include <Stepper.h>

//

const int stepsPerRevolution = 200; // change this to fit the number of steps per revolution for your motor

// System clock selection is performed on startup,

// however the internal RC 8 MHz oscillator is selected as default CPU clock on reset.

// PA13 SWDIO, PA14 SWCLK, PC14/PC15 OSC, // USART on pins PA14/PA15 or PA9/PA10.

```
// initialize the stepper library on pins 8 through 11:
Stepper myStepper(stepsPerRevolution, PA8, PA7, PA12, PA11);
int stepCount = 0;
                      // number of steps the motor has taken
static uint8 t Digit5th = 0; // Defines the 5th digit weight
static uint8 t Digit4th = 0; // Defines the 4th digit weight
static uint8 t Digit3rd = 0; // Defines the 3rd digit weight
static uint8 t Digit2nd = 0; // Defines the 2nd digit weight
static uint8 t tempC = 0; // Defines the last digit weight
void setup() {
Serial.begin(2400);
                      // initialize the serial port:
                            pinMode(PA1, OUTPUT); pinMode(PA2, OUTPUT);
pinMode(PAO, OUTPUT);
                                                                                    pinMode(PA3,
OUTPUT);
                            pinMode(PA5, OUTPUT);
pinMode(PA4, OUTPUT);
//pinMode(PC0, OUTPUT);
                             pinMode(PC1, OUTPUT); pinMode(PC2, OUTPUT);
pinMode(PC3, OUTPUT);
//pinMode(PC4, OUTPUT);
 // pinMode(PC5, OUTPUT);
pinMode(PC13, OUTPUT);
Serial.println("....");
Serial.print("Baud Rate 2400: ");
Serial.println("STM32F401RCT6 with Arduino");
Serial.println("23 October 2024");
Serial.println("STM32F401RCT6.inO");
Serial.println("....");
digitalWrite(PC13, HIGH); delay(400); digitalWrite(PC13, LOW); delay(400);
}
void loop() {
 //digitalWrite(PC0, !digitalRead(PC0)); delay(50);
 //digitalWrite(PC1, !digitalRead(PC1)); delay(50);
 //digitalWrite(PC2, !digitalRead(PC2)); delay(50);
 //digitalWrite(PC3, !digitalRead(PC3)); delay(50);
 // digitalWrite(PC4, !digitalRead(PC4)); delay(50);
 // digitalWrite(PC5, !digitalRead(PC5)); delay(50);
 digitalWrite(PC13, !digitalRead(PC13)); delay(50);
 digitalWrite(PA0, !digitalRead(PA0)); delay(50);
 digitalWrite(PA1, !digitalRead(PA1)); delay(50);
 digitalWrite(PA2, !digitalRead(PA2)); delay(50);
 digitalWrite(PA3, !digitalRead(PA3)); delay(50);
 digitalWrite(PA4, !digitalRead(PA4)); delay(50);
 digitalWrite(PA5, !digitalRead(PA5)); delay(50);
 myStepper.step(1);
                       // step one step:
 Serial.print("steps:"); Serial.println(stepCount);
 stepCount++; delay(50);
```

```
for (int i=0; i<30; i++) {
Serial.print(Digit5th, DEC);
Serial.print(Digit4th, DEC);
Serial.print(Digit3rd, DEC);
Serial.print(Digit2nd, DEC);
Serial.println(tempC, DEC);
++tempC; // increment last digit weight by one and returns the new value of x
if (tempC > 9) { tempC = 0; ++Digit2nd; }
                                                    //last digit statement(s)
if (Digit2nd > 9) { Digit2nd = 0; ++Digit3rd; }
                                                    //2nd digitstatement(s)
if (Digit3rd > 9) { Digit3rd = 0; ++Digit4th; }
                                                   //3rd digitstatement(s)
if (Digit4th > 9) { Digit4th = 0; ++Digit5th; }
                                                   //4th digitstatement(s)
if (Digit5th > 6) { Digit5th = 0; }
                                              //5th digits max = 60 tonne
}
}
```