

EXPRESS DIAGNOSTICS

Advanced Vehicle Diagnostic & ADAS Analysis Report

Report Type	DTC Analysis & ADAS Operations Review
DTCs Found	4
Generated By	Express Diagnostics

Scan Summary

The scan report was processed and 4 Diagnostic Trouble Code(s) were identified. The following explanations are intended to support repair planning, ADAS documentation, and post-repair verification.

Detected DTCs & Professional Analysis

DTC	B1206
Description	Power window(P/W) master switch electronic control
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	• Wiring or connector issue • Low voltage event • Sensor or module fault • Commu
Recommended Actions	• Perform pinpoint diagnostics • Inspect wiring and connectors • Repair root cause
ADAS / Safety Impact	ADAS impact should be verified based on the affected module and OEM repair procedures.

DTC	B2312
Description	Power window switch of left rear door fault
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	• Wiring or connector issue • Low voltage event • Sensor or module fault • Commu
Recommended Actions	• Perform pinpoint diagnostics • Inspect wiring and connectors • Repair root cause
ADAS / Safety Impact	ADAS impact should be verified based on the affected module and OEM repair procedures.

DTC	B2312
Description	Power window switch of passenger door fault
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	• Wiring or connector issue • Low voltage event • Sensor or module fault • Commu
Recommended Actions	• Perform pinpoint diagnostics • Inspect wiring and connectors • Repair root cause
ADAS / Safety Impact	ADAS impact should be verified based on the affected module and OEM repair procedures.

DTC	B15DB
Description	Telematics transceiver disconnected
What This Means	This code indicates a detected fault in the related vehicle system or module.
Possible Causes	• Wiring or connector issue • Low voltage event • Sensor or module fault • Commu
Recommended Actions	• Perform pinpoint diagnostics • Inspect wiring and connectors • Repair root cause

ADAS / Safety Impact	ADAS impact should be verified based on the affected module and OEM repair procedures.
-----------------------------	--

Required / Recommended ADAS Operations

- 1 ADAS system verification per OEM procedures if repairs affect sensors, cameras, radar, suspension, steering, or body structure
- 2 Post-repair road test and functional validation
- 3 Pre-scan and post-scan documentation

Insurance / Repair Documentation Statement

Fault codes and ADAS-related module concerns must be evaluated according to OEM repair procedures. Clearing codes alone does not confirm system integrity. After repairs, affected systems should be verified through post-scan documentation, calibration when required, and functional road testing.

EXPRESS DIAGNOSTICS — Precision. Safety. Confidence.