



Shop Name: Express Recalibrations

Tel: 502-234-2327

Email: service@expdiag.com

Address: 4616 Pinewood Road

Report ID: MAXIA20260505082610

Test Time: 2026-05-05 08:26:10

Technician: juan

2020 Toyota Pre-scan Report

Vehicle Information

2020/Toyota/Highlander/--

VIN: 5TDGZRBH9LS501143

Odometer Reading: 87174miles

License Plate: --

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiSys MS909&ADAS

Version: V4.30-7.40

Serial Number: VA9GR7V01305

Repair Order Number: HIGHLANDER
26848 TOYOTA

Insurance Information

Insured name:--

Claim number:--

Contact Information:--

City state zip:--

Insurance company:--

Address:--

Primary impact:--



System Scanned (36)

System	Calibration	Status/DTC
Engine		✓ 0
Transmission		✓ 0
SRS airbag		✓ 0
Combination meter		✓ 0
Brake/EPB		✓ 0
Tire pressure monitor		✓ 0
Main body		✗ 2
Driver door motor		✓ 0
Sliding roof		✓ 0
Right rear door motor		✓ 0
Left rear door motor		✗ 1
Passenger door motor		✗ 1
Back door		✓ 0
Air conditioner		✓ 0
Front radar sensor	ADAS	✓ 0
Navigation system		✗ 1
Starting control		✓ 0

Telematics		✓ 0
Occupant detection		✓ 0
Power source control		✓ 0
Smart key		✓ 0
Blind spot monitor (BSM) master	ADAS	✓ 0
Front recognition camera (Front lighting control)	ADAS	✓ 0
Blind spot monitor (BSM) slave	ADAS	✓ 0
Stop & start		✓ 0
Radar cruise 1	ADAS	✓ 0
Radar cruise 2	ADAS	✓ 0
4WD		✓ 0
EMPS		✓ 0
Front recognition camera	ADAS	✓ 0
Lane control	ADAS	✓ 0
Steering angle sensor (SAS)		✓ 0
Pre-Collision system	ADAS	✓ 0
Central gateway		✓ 0
Master switch		✓ 0
Road sign assist	ADAS	✓ 0

Pre-scan DTC (5)

Main body (2 DTCs)

DTC	Description	Status
B1206	Power window(P/W) master switch electronic control unit(ECU) communication stop	History
B2321	Driver door motor electronic control unit(ECU) communication stop	History

Left rear door motor (1 DTC)

DTC	Description	Status
B2312	Power window switch of left rear door fault	History

Passenger door motor (1 DTC)

DTC	Description	Status
-----	-------------	--------

B2312	Power window switch of passenger door fault	History
-------	---	---------

Navigation system (1 DTC)

DTC	Description	Status
B15DB	Telematics transceiver disconnected	History

Pre-scan Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.