How to Flash LIANUMPAD

1. Download QMK TOOLBOX, in this link https://github.com/qmk/qmk_toolbox/releases, adjust it to the OS you are using
2. Install QMK TOOLBOX and install all driver
3. Download File Hex
4. Insert file hex and check box Auto-Flash



5. Pick your LIANUMPAD, press the button marked, then connect it to your PC's USB and immediately release the button



6.
7. then there will be a sign that you have successfully flashed
8. If it fails, you can repeat the steps above