

# COOLING TOWER INSPECTION REPORT

Observed conditions and recommended services

## Inspection overview

Components documented: water pump, fan, housing, and fan grille.

The submitted photographs document exterior views, the grille, pump components, and electrical enclosures.

## Findings

1. Suspected algae or other microbial growth was present at inspection.
2. Mineral buildup and scaling were observed on the cooling tower grille.

## Recommended services

1. Clean affected areas and request a water treatment assessment of growth and scaling.
2. Prepare and apply an anticorrosive coating to the unit base and exterior.
3. Install vibration absorbers and verify proper fit and operation.


## Inspection note

The extent of microbial growth and the cause of scaling require further evaluation.

Photographs show visible conditions; they do not establish operational performance.



01 Fan and cooling tower exterior



02 Grille, housing, and base

# COOLING TOWER INSPECTION REPORT

Photo documentation | Grille and pump



03 Grille and lower housing



04 Grille close-up



05 Water pump and strainer



06 Internal pump component




# COOLING TOWER INSPECTION REPORT


Photo documentation | Equipment details



07 Pump motor identification plate



08 Electrical enclosure interior



09 Electrical enclosure interior

Equipment photos are included for reference.  
No electrical diagnosis is stated in this report.