

**KLR Automotive****Phone:** +61245775010**Email:** service@klr.com.au**Web:** <http://klr.com.au>**ABN:** 58633010965

Invoice

INV1092

Date: 21/08/2024**Bill To**

Simon Barclay
Simon Barclay
54 Eliza St
Clayfield QLD 4011
Australia

Ship To

Simon Barclay
54 Eliza St
Clayfield QLD 4011
Australia

Terms	Due Date	Vehicle (Automotive)
Payment Prior to Delivery	21/08/2024	SALLDHA87XA176069

Item	Quantity	Units	Rate	Amount
TF562 Front Downpipe, Decat, Def/D2 Td5 Front Downpipe, Decat, Def/D2 Td5	1	EA	\$0.00	\$265.00
LPX100590 Td5 Bypass Oil Filter Td5 Bypass Oil Filter	1	EA	\$10.91	\$10.91
ESR4686 Td5 Fuel Filter Td5 Fuel Filter	1	EA	\$22.73	\$22.73
LR027408 Air Filter Td5 Defender, Discovery 2 and Range Rover P38A Air Filter Td5 Defender, Discovery 2 And Range Rover P38A	1	EA	\$15.91	\$15.91
ERR6299 Rotor Oil Filter Td5 Rotor Oil Filter Td5	1	EA	\$20.00	\$20.00
C15W30 Engine Oil, Synthetic 5W30 Engine Oil, Synthetic 5W30	7.7	EA	\$19.95	\$153.62
ENVIRO LEVY Environmental Levy Environmental Levy	1	EA	\$22.00	\$22.00
Labour Labour Charge Supply and fit front decat pipe due to old flex joint splitting.	1	Hr	\$175.00	\$175.00
Labour Labour Charge Carried as service as required, replaced engine oil and filter, replaced air filter, replaced fuel filter.	1.5	Hr	\$175.00	\$262.50

Bank Account Details:

Account Name: KLR Automotive PTY LTD
BSB: 012874
Account #: 472434595

Subtotal \$947.67**GST Total** \$94.76**AUD Total** **\$1,042.43****Balance** **\$1,042.43**

INV1092



KLR Automotive

Phone: +61245775010

Email: service@klr.com.au

Web: <http://klr.com.au>

ABN: 58633010965

Invoice

INV1092

Date: 21/08/2024

Customer Notes:



Pay with the QR code, or click this [secure link](#). You can also copy the link to clipboard.



INV1092