

**KLR Automotive****Phone:** +61245775010**Email:** service@klr.com.au**Web:** <http://klr.com.au>**ABN:** 58633010965

Invoice

INV6266

Date: 08/09/2025**Bill To**

Simon Barclay
Simon Barclay
UNIT 7, 140 FRANCIS STREET
RICHMOND NSW 2753
Australia

Ship To

Simon Barclay
UNIT 7, 140 FRANCIS STREET
RICHMOND NSW 2753
Australia

Terms	Due Date	Vehicle (Automotive)
Payment Prior to Delivery	08/09/2025	SALLDHA87XA176069

Item	Quantity	Units	Rate	Amount
KLR-SK001 Service Kit - Discovery 2 & Defender Td5	1		\$90.91	\$90.91
SBI12 Redarc Smart Start SBI 12V Battery Isolator Redarc Smart Start Sbi 12V Battery Isolator	1	EA	\$172.50	\$172.50
JAE000030 Defender Dash Vent Sealing Rubber Defender Dash Vent Sealing Rubber	2	EA	\$25.45	\$50.90
LDI100030 Td5 Cam Oil Seal Td5 Cam Oil Seal	1	EA	\$12.696	\$12.70
AWR2215 Defender/110 Heater Intake Grille (Left Hand) Defender/110 Heater Intake Grille (Left Hand)	1	EA	\$14.48	\$14.48
AWR2214 Perentie Right Hand Front Guard Upper Grille Perentie Right Hand Front Guard Upper Grille	1	EA	\$21.82	\$21.82
BTD1 BTD/Non-Stock Item MHK100620 Air Flow Meter TD5	1		\$350.00	\$350.00
BTD1 BTD/Non-Stock Item ERR7266 Cam Cover Grommets	13		\$10.00	\$130.00
BTD1 BTD/Non-Stock Item 6066 Glow Plug TD5	4		\$38.50	\$154.00
BTD1 BTD/Non-Stock Item ERR53845KIT AMC Head Bolts	1		\$390.00	\$390.00
BTD1 BTD/Non-Stock Item LDI100030 Plug Cam Seal	1		\$35.00	\$35.00
BTD1 BTD/Non-Stock Item LJQ100940 Seal/Valve	10		\$9.09	\$90.90
BTD1 BTD/Non-Stock Item ERR7004 O-Ring Injector	5		\$12.00	\$60.00
BTD1 BTD/Non-Stock Item ERR6768 Gasket/Turbo	1		\$15.00	\$15.00
BTD1 BTD/Non-Stock Item ESR3737 Gasket/Exhaust	1		\$11.36	\$11.36
BTD1 BTD/Non-Stock Item LKJ000010 Gasket/Inlet/TD5	1		\$27.27	\$27.27
BTD1 BTD/Non-Stock Item ERR6417 Washer-Inj-Copper	5		\$12.00	\$60.00
BTD1 BTD/Non-Stock Item ERR7094 Gasket/Cover/TD5	1		\$55.00	\$55.00



INV6266

**KLR Automotive****Phone:** +61245775010**Email:** service@klr.com.au**Web:** <http://klr.com.au>**ABN:** 58633010965

Invoice

INV6266

Date: 08/09/2025

Item	Quantity	Units	Rate	Amount
BTD1 BTD/Non-Stock Item LKG100470 Gasket/Exhaust/TD5	1		\$30.00	\$30.00
BTD1 BTD/Non-Stock Item LVJ000010 Elbow Gasket	1		\$5.00	\$5.00
BTD1 BTD/Non-Stock Item ADU6847L Sealing Washer	2		\$5.50	\$11.00
BTD1 BTD/Non-Stock Item LVB000250 TD5 Head Gasket 1 hole 1.27mm	1		\$145.00	\$145.00
BTD1 BTD/Non-Stock Item ERR6761 O/Ring/Special	1		\$2.41	\$2.41
BTD1 BTD/Non-Stock Item MSX000010 Gasket/Regulator	1		\$10.65	\$10.65
BTD1 BTD/Non-Stock Item MAS1-HD Stud 10x1.5x18mm Heavy Duty	8		\$9.09	\$72.72
BTD1 BTD/Non-Stock Item MNS3 Nut/Exhaust 10x1.5	8		\$2.64	\$21.12
BTD1 BTD/Non-Stock Item TE108052 Exhaust Manifold Studs	2		\$0.78	\$1.56
BTD1 BTD/Non-Stock Item LR019197 Nut Exhaust Manifold TD5	2		\$2.00	\$4.00
BTD1 BTD/Non-Stock Item REPSOL/ELITE Evolution 5W/40	7		\$15.68	\$109.76
BTD1 BTD/Non-Stock Item STC50529 1L Bottle, Ext Coolant	4		\$25.00	\$100.00
BTD1 BTD/Non-Stock Item ERR7225 Cylinder Head Valve Guide TD5	1		\$35.00	\$35.00
BTD1 BTD/Non-Stock Item AMR6103 Modified TD5 Injector Harness	1		\$250.00	\$250.00
BTD1 BTD/Non-Stock Item ERR5369 Seal/Cam/TD5	1		\$12.50	\$12.50
BTD1 BTD/Non-Stock Item HEAD SERVICE Cylinder Head Service	1		\$895.00	\$895.00
Labour Labour Charge Check oil Leak, suspect rear main, remove transmission, found oil tracking from higher, suspect head gasket on drivers corner leaking, remove cylinder head, Sublet cylinder head for machining, replace exhaust guides, Supply and fit modified exhaust studs, straghten exhaust manifold, replace all injector washers and seals, assemble cylinder head, replaced all head bolts and seals, pressure test to check for leaks, all ok. Replaced engine oil, air flow meter reading incorrect, install new air flow meter. road test vehicle, all ok	30	Hr	\$175.00	\$5,250.00
C15W30 Engine Oil, Synthetic 5W30 Engine Oil, Synthetic 5W30	7	EA	\$19.95	\$139.65
AUSTCOOL Coolant Concentrate, 1 Litre Coolant Concentrate, 1 Litre	5	EA	\$17.95	\$89.75



INV6266



KLR Automotive
Phone: +61245775010
Email: service@klr.com.au
Web: <http://klr.com.au>
ABN: 58633010965

Invoice

INV6266
Date: 08/09/2025

Item	Quantity	Units	Rate	Amount
Labour Labour Charge Supply and fit redarc smart sbi12	1	Hr	\$175.00	\$175.00
Labour Labour Charge replace vent sealing rubbers.	1.2	Hr	\$175.00	\$210.00

Bank Account Details:

Account Name: KLR Automotive PTY LTD
BSB: 012874
Account #: 472434595

Subtotal \$9,311.96

GST Total \$931.22

AUD Total **\$10,243.18**

Balance **\$10,243.18**

Customer Notes:



Pay with the QR code, or click this [secure link](#). You can also copy the link to clipboard.



INV6266