

calculation.

```
digitalWrite (3, HIGH);  
delay (20);  
digitalWrite (3, LOW);  
delay (20);
```

} transition $\rightarrow$ 1 step

$\therefore$ 1 step $\rightarrow$ 40 ms.

200 steps (for 360°) $\rightarrow$ 8000 ms OR 8s, (full step mode)

$\therefore$, for 1 complete Revolution, motor will take 8 seconds.

OR ~~Bar~~ ~~WAP~~: in 1 second, motor goes 25 steps.
(1s : $\frac{200}{8}$ steps)