ORIGINATOR Scott P		SERV. MGR. 57-8	TINC. BY
SUPERVISOR	MFG MGR.	PROD. CTRL.	снк. ву
ENG.MGR.	PROD. ENG.	MATL. CTRL.	Steven T. Lande
PRIORITY:  EMERGENCY URGENT STANDARD	TYPE OF CHANGE:  RELEASE COS  DESIGN CALL  RECORD OTH	OUCTION INVENTOR	RETROFIT TO FIELD  TO OTHER
MODEL NO. ASSY. NO. 2440 . 2-367 REASON FOR CHANGE:	InTerlink force	2400 PCB #3	Assembly
only Take 1.5		e sensing resist. Tive element.	iv malevial c
1. Cut The Two 2. Jump from ( 3. Add 6.8K (R-	Traces connect  Traces connect  1310 pin 8 To low  079) from +12 U  008) from arous	To T306 pin	LEMENT SHEET.) 2 To +12 V T Trimmer 1 + 2
	4 from 2K (		(R-014)

## SEQUENTIAL ECT SUPPLEMENT

ECR NO. 739

SHT. 2 OF 6 ENGINEERING BOM DATA A C D ASSY. PART QTY INC. DESCRIPTION NO. NO. WAS IS BY 2-367 R-079 6.8K V4W 576 CAN! 2-367 R-008 2 cam 11 1/4 (1) 5% R-010 2k 1/4W 576 agm 2-367 R-014 CAM 0 15K 1/4W 5%

\*A-ADD \*C-CHANGE

\*D-DELETE

ECO NO: 702





