Scott P	. (	SERV. MGR.	5-7-89	INC. BY
SUPERVISOR	MFG: MGR. +5.7.87	PROD. CTRL	19.87	СНК. ВУ
ENG.MGR.	PROD. ENG.	MATL.CTRL.	- Marie Company	Stem T. Larlet
PRIORITY:	TYPE OF CHANGE:		AFFECTING:	
EMERGENCY URGENT STANDARD	RELEASE COST DESIGN RED RECORD OTH	UCTION L	NEW PROD. INVENTORY TEST EQUIP	RETROFIT   OTHER
MODEL NO. ASSY. NO. 2 400 Z-368 REASON FOR CHANGE:	<b>-</b> -	2400	PCB 44	Assembly
can only Ta	ke 1.5V across	They	esistive	isler material
1. Jul Ivace	NGES: (IF MORE SPACE)	IS REQUIRED	, USE SUPPL	EMENT SHEET.)
2. Add 6.8K	(R-079) frem	+12 V Ta	J401	7 h 3 +4
3. Add 1K (	R-008) from a	round	To J 401	oin 3+4
	150 0		To 15K (	R-014)

SEQUENTIAL ECT SUPPLEMENT SHT. 2 OF 3

				ENGIR	JEEP	4114	BOM	DATA	
* A	* * D		ASSY.	PART NO.	QTY WAS IS		DESCRIPTION		INC. BY
X			2-368	R-079	0		6.8K 1/4U	570	Office
	X		2-368	R-008	6		IK KHU	570	agre-
	X		2-368	R-010	12		2K Valu	5%	igns-
X			2-368	R-014	0		15K U4M	1 5%	agm
								*	
								*	

\*A-ADD \*C-CHANGE

\*D-DELETE

ECO NO: 701



