De Young Properties

| Lot 130/Tract 0273 | Items: 12 | CH Items: 0 | Checklist Inspections: 258 |
|---|---|--|-------------------------------|
| Cabinet Connection | | | |
| Code: J_162 Category: Cabinets Partner: Cabinet Connection | Location: Bedroom 3 Type: Missing middle trim under cabinet | Description: Missing middle trim under cabinet | Incomplete |
| Code: J_164 Category: Cabinets Partner: Cabinet Connection | Location: Bathroom 1 Type: Cabinet missing trim or other parts | Description: Missing middle support under both cabinets in master bath | Incomplete |
| Code: ZZ_624 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks | Description: Cabinet scratches on 2nd cabinet to the right of stove | Incomplete |
| Code: ZZ_625 Category: Cabinets Partner: Cabinet Connection | Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks | Description: Cabinet scratches above microwave | Incomplete |
| Elia Painting | | | |
| Code: ZZ_626 Category: Paint Partner: Elia Painting | Location: Great Room Type: Caulking touch-up required at baseboard, window frame, trim/door frame, or wall corners | Description: Caulking void to the left of media outlet in great room under baseboard | Incomplete |
| Matthews Quality Co | onstruction | | |
| Code: J_161 Category: Millwork Partner: Matthews Quality Construction | Location: Bedroom 3 Type: Missing bypass guide | Description: Missing bypass guide at closet doors | Incomplete |
| Ohanians Drywall | | | |

| Lot 130/Tract 0273 | Items: 12 | CH Items: 0 | Checklist Inspections: 258 |
|--|---|---|-------------------------------|
| Code: Z_009 Category: Drywall Partner: Ohanians Drywall | Location: Great Room Type: Drywall has crack, gash, hole, and/or gouge | Description: Drywall void near Electrical switch near slider | Incomplete |
| Code: ZZ_627 Category: Drywall Partner: Ohanians Drywall | Location: Garage Type: Drywall has crack, gash, hole, and/or gouge | Description: Please patch drywall near outlet in garage on back wall | Incomplete |
| Code: ZZ_630 Category: Drywall Partner: Ohanians Drywall | Location: Garage Type: Drywall has crack, gash, hole, and/or gouge | Description: Patch drywall void near irrigation timer | Incomplete |
| Premier Door | | | |
| Code: J_163 Category: Millwork Partner: Premier Door | Location: Bathroom 2 Type: Missing By-pass Guide | Description: Missing bypass guide in bedroom two | Incomplete |
| Tri Valley Plastering | & Drywall | | |
| Code: ZZ_628 Category: Stucco Partner: Tri Valley Plastering & Drywall | Location: Exterior Type: Chip/crack/gouge | Description: patch stucco on left side of home near condensation line | Incomplete |
| Code: ZZ_629 Category: Stucco Partner: Tri Valley Plastering & Drywall | Location: Exterior Type: Chip/crack/gouge | Description: Patch stucco hole near man door | Incomplete |