
11:aclNW(internet,jump_server,tcp,445):1
12:malicious(internet):1
13:attackerLocated(internet):1
10:RULE 0 (Direct network reachability via permissible ACL policy):0
9:netAccess(internet,internet,jump_server,tcp,445):0
14:vulHost(jump_server,cve_2022_26809,rpc_service,remoteExploit,privEscalation):1
15:networkService(jump_server,rpc_service,tcp,445,admin):1
8:RULE 2 (Remote code execution via vulnerable network service):0
5:networkService(plc_l1_1,modbus_service,tcp,502,root):1
6:aclNW(jump_server,plc_l1_1,tcp,502):1
7:execCode(jump_server,admin):0
4:RULE 5 (Unauthorized industrial command injection into PLC over unauthenticated Modbus/TCP):0
3:unauthorizedControl(plc_l1_1):0
18:isSlave(drive_area_1_1,bus_area_1):1
19:isMaster(plc_l1_1,bus_area_1):1
20:l2Connection(jump_server,drive_area_1_1,bus_area_1,profinet,bus):1
2:RULE 6 (Unauthorized control of industrial controller yields root execution privilege):0
17:RULE 8 (Unauthorized physical drive actuation via unauthenticated PROFINET bus link):0
1:execCode(plc_l1_1,root):0
16:physicalDriveControl(jump_server,drive_area_1_1):0