
7:aclNW(internet,jump_server,tcp,445):1
9:attackerLocated(internet):1
8:malicious(internet):1
6:RULE 0 (Direct network reachability via permissible ACL policy):0
5:netAccess(internet,internet,jump_server,tcp,445):0
10:vulHost(jump_server,cve_2022_26809,rpc_service,remoteExploit,privEscalation):1
11:networkService(jump_server,rpc_service,tcp,445,admin):1
4:RULE 2 (Remote code execution via vulnerable network service):0
19:networkService(plc_l1_1,modbus_service,tcp,502,root):1
20:aclNW(jump_server,plc_l1_1,tcp,502):1
3:execCode(jump_server,admin):0
12:aclNW(jump_server,plc_l1_1,tcp,4840):1
13:vulHost(plc_l1_1,cve_2022_25888,opcua_server,remoteExploit,dos):1
14:networkService(plc_l1_1,opcua_server,tcp,4840,root):1
18:RULE 5 (Unauthorized industrial command injection into PLC over unauthenticated Modbus/TCP):0
2:RULE 7 (Denial of Service against Level 1 OPC UA server disabling control-loop communications):0
17:unauthorizedControl(plc_l1_1):0
1:dos(internet,plc_l1_1):0
16:RULE 6 (Unauthorized control of industrial controller yields root execution privilege):0
15:execCode(plc_l1_1,root):0