
6:malicious(internet):1
11:aclNW(internet,jump_server,tcp,445):1
12:attackerLocated(internet):1
10:RULE 0 (Direct network reachability via permissible ACL policy):0
9:netAccess(internet,internet,jump_server,tcp,445):0
13:vulHost(jump_server,cve_2022_26809,rpc_service,remoteexploit,privescalation):1
14:networkService(jump_server,rpc_service,tcp,445,admin):1
8:RULE 2 (Remote code execution via vulnerable network service):0
5:aclNW(jump_server,plc_l1_1,tcp,4840):1
7:execCode(jump_server,admin):0
20:networkService(plc_l1_1,modbus_service,tcp,502,root):1
21:aclNW(jump_server,plc_l1_1,tcp,502):1
4:RULE 1 (Network reachability from compromised intermediate host):0
19:RULE 5 (Unauthorized industrial command injection into PLC over unauthenticated Modbus/TCP):0
3:netAccess(internet,jump_server,plc_l1_1,tcp,4840):0
15:vulHost(plc_l1_1,cve_2022_25888,opcua_server,remoteexploit,privescalation):1
16:networkService(plc_l1_1,opcua_server,tcp,4840,root):1
18:unauthorizedControl(plc_l1_1):0
2:RULE 2 (Remote code execution via vulnerable network service):0
17:RULE 6 (Unauthorized control of industrial controller yields root execution privilege):0
1:execCode(plc_l1_1,root):0