

## Status of MACRO PMT pressure tests at SAB

Logan Lebanowski, Shih-Kai Lin

University of Houston

Sep 23, 2010



## pressure test results

- ▶ As of September 23, we have passed 47 of 50 PMTs.
- ▶ 11 PMTs were tested during the past week (September 16 September 22). PMT 8870 had a hole in the cable jacket. It was fixed and tested again.

SN mass	s (g)   pres	sure (psig)	test time (h:m)	result
7851 56	54	12.1	14:48	PASS <sup>1</sup>
7127 58	32	12.2	8:51	$PASS^2$
7820 595	5.5	12.0	14:44	$PASS^3$
7267 643	3.5	12.0	8:44	$PASS^2$
7934 60	)9	12.0	14:48	FAIL <sup>4</sup>
8430 55	54	12.0	47:23	FAIL <sup>5</sup>
8870 587	7.5	12.0	7:27	$PASS^2$
7899 56	56	12.0	16:24	PASS <sup>3</sup>
7765 57	73	12.1	7:05	PASS <sup>3</sup>
7471 60	01	12.0	14:56	PASS <sup>1</sup>

Table 1: pressure test result: For PASS/FAIL reasons, please see the table in the next slide.



## PASS/FAIL reasons

number	reason
1	Cable dry. No leaks or cracks.
2	1+Some water penetrated the mastic tape seal of the cable
	strain relief plug, but did not penetrate the UW cable plug.
3	Moisture on the SHV end in the sealing tube. Conductivity
	test performed.
4	Acrylic cap contains much water.(see photo)
5	A big crack and a little hole in the PMT. Photocathode was
	gone.(see photo)

Table 2: PASS/FAIL reasons



## photos: PMT 7934

