

IRONMIND — Maintenance Decision Report

Generated: 12 June 2026, 19:50 IST

Field	Value
Asset ID	BF_FAN_12
Fault Type	Bearing Wear / Vibration Anomaly
Risk Level	CRITICAL
RUL (days)	18
Root Cause	Fatigue induced by continuous high-stress operation
Report Date	12/06/2026

Maintenance Plan

1. Initiate LOTO procedures
2. Inspect drive-end bearing
3. Replace SKF bearing if radial clearance exceeds threshold

Cost Analysis

Decision Option	Cost Estimate
Planned maintenance now	■1.6Cr
Expected cost if failure occurs	■4.5Cr
Savings from acting now	■2.9Cr