

## **Product:**

### **Industrial Drilling Machine**

## **Causes of Failure:**

- **High Temperature** → overheating damages internal parts
  - **High Rotational Speed** → increases wear and tear
  - **Excessive Torque** → puts stress on the machine
- **Tool Wear** → old tools reduce efficiency and cause breakdown
  - **Poor Maintenance** → leads to unexpected failure

## **Suggested Fix:**

- Regular maintenance and inspection
- Use cooling systems to control temperature
  - Replace worn tools on time
- Monitor speed and torque using sensors

## **Conclusion:**

Machine failure mainly occurs due to high temperature and tool wear. By using proper monitoring and regular maintenance, failures can be reduced and machine performance can be improved.