## **INT 10 - Video BIOS Services**

## For more information, see the following topics:

Warning: Some BIOS implementations have a bug that causes register BP to be destroyed. It is advisable to save BP before a call to Video BIOS routines on these systems.

```
- registers CS, DS, ES, SS, BX, CX, DX are preserved unless explicitly changed
```

- see <u>INT 1F INT 1D INT 29 INT 21,2 INT 21,6 INT 21,9</u>

1 of 1 01/24/2007 02:33 PM