

Report Details

Report ID	FR-2026-009
Location	Richmond - 5800 Geary Blvd
Machine	CBM-007 DeLonghi Maestosa
Serial No	DEL-MAE-20230214-007
Date	2026-07-16
Reported by	Omar F. (Location Manager)

Fault Description

Fault code M-08 (Milk System Underperformance). The automatic milk frother is producing thin, under-textured microfoam and occasionally fails to purge. Cappuccino quality complaints on 14 and 15 Jul. Suspected clogged milk circuit or worn frother valve.

Requested Action / Technician Notes

- Deep-clean the milk circuit and inspect the frother valve (DEL-MAE-FRVALVE).
- Retrain staff on the daily milk-system rinse cycle.
- Medium priority - quality impact during peak hours.