


Report Details

Report ID	FR-2026-002
Location	North Beach - 585 Columbus Ave
Machine	CBM-009 Siemens EQ.9 Plus Connect
Serial No	SIE-EQ9-20190812-009
Date	2026-07-05
Reported by	James L. (Location Manager)

Grind Time - Double Shot



Fault Description

Fault code W-12 (Grinder Motor Degradation). Grind time for a double shot has increased from a normal 8 seconds to 14 seconds. First occurrence 15 Jun 2026, partially resolved, then returned 5 Jul 2026. The machine is 7 years old with no major overhaul on record. Grinder burrs are likely worn beyond the service threshold.

Requested Action / Technician Notes

- Schedule grinder burr replacement and a full motor inspection.
- No urgent production impact yet, but further degradation is expected within 2-3 weeks.
- Part: grinder burr set (SIE-EQ9-BURR-STD).