

Report Details

|             |                                     |
|-------------|-------------------------------------|
| Report ID   | FR-2026-006                         |
| Location    | SOMA - 199 5th St                   |
| Machine     | CBM-006   Siemens EQ.9 Plus Connect |
| Serial No   | SIE-EQ9-20200418-006                |
| Date        | 2026-07-20                          |
| Reported by | Diego R. (Location Manager)         |

Brew Pressure - Recent



Fault Description

Fault code E-07 (Pressure Sensor Fault) triggered on 2026-07-20 and remains unresolved. Brew pressure dropped to 8.0 bar. This is the same fault family currently affecting CBM-003 at Mission; both are Siemens EQ.9 units of similar age. Worth checking whether a batch or firmware issue links them.

Requested Action / Technician Notes

- Inspect pump and pressure line; compare findings with CBM-003.
- Parts likely: SIE-EQ9-PUMP-003, SIE-EQ9-PL-KIT.
- Flag to fleet lead: two EQ.9 pressure faults within 48 hours.