

### Report Details

|             |                                     |
|-------------|-------------------------------------|
| Report ID   | FR-2026-010                         |
| Location    | South Bay (Online fulfilment)       |
| Machine     | CBM-012   Siemens EQ.9 Plus Connect |
| Serial No   | SIE-EQ9-20210510-012                |
| Date        | 2026-07-11                          |
| Reported by | Ops Monitoring (automated)          |

### Fault Description

Fault code C-01 (Connectivity Dropout). The machine's telemetry uplink dropped intermittently over 3 days, creating gaps in the fault-event stream. Brewing was unaffected; this is a monitoring/reporting issue rather than a mechanical one.

### Requested Action / Technician Notes

- Check the network module and Wi-Fi signal strength at the fulfilment site.
- Update the connectivity firmware to the latest EQ.9 build.
- Low priority - no brewing impact, but restores telemetry visibility.