

Sunny Bay Roastery - Fault Report

Report Details

Report ID:	FR-2026-002
Location:	North Beach - 585 Columbus Ave
Machine:	CBM-009 Siemens EQ.9 Plus Connect
Serial No:	SIE-EQ9-20190812-009
Date:	2026-07-05
Reported by:	James L. (Location Manager)
Priority:	MEDIUM

Fault Description

Fault code W-12 (Grinder Motor Degradation). Grind time increased from normal 8 seconds to 14 seconds for a double shot. First occurrence 15 Jun 2026, partially resolved, returned 5 Jul 2026. Machine is 7 years old with no major overhaul on record. Grinder burrs likely worn beyond service threshold.

Requested Action / Technician Notes

Schedule grinder burr replacement and full motor inspection. No urgent production impact at this time but further degradation expected within 2-3 weeks.