

Shafts & Winders Performance

Weekly Tons/Hr

Target: 523

266

Weekly RW Availability (%)

Target: 95%

96.12%
~~97.53%~~

✓ Highlights

- Investigation on NLTI_FAC_Completed
- Possible solution identified with Safewind Control Systems to resolve "Tip and Start" issue
- 1 x WED Identified

⚠ Lowlights

- ~~SR 0030 Scaler incident (FAC)~~
- Lamproom Findings Identified with Quarterly Audit
- Changehouse Issues at NCh3

🕒 Emerging Issues

- Low compliment of Fitters and Riggers in Mechanical Section continues to put pressure on the Section

🔑 Priorities

- Address Lamproom and Changehouse findings from audits.
- Finalize solution for "Tip and Start" issue with Safewind.
- ~~Follow up on SR 0030 incident investigation actions.~~


Nchwaning 3 Performance Overview

✓ Safety
Clear

Weekly Avg.
87%
(Target: 85%)

⚙ Compliance
No major compliance
issues reported for
standard fleet.

Equipment Availability



Key Breakdowns

HD0056

- Feed cylinder issues

~~DT047~~ **DT0147**

- TTS and flat tyre replacement

~~DT0103~~ **DT109**

- Strata issues, swelling parts

BEV Fleet

📦 BEV Availability (Wk 5)

- DT BEV: 72% (Below Target)
- FL BEV: 72% (Below Target)

⚡ BEV Service Compliance

- DT BEV: None scheduled
- FL BEV: ~~0%~~ None Scheduled.

BEV Availability by Equipment Type

DT BEV

Target: 85%

72%

FL BEV

Target: 85%

72%

Key BEV & Battery Themes

Key Breakdowns:

- DT0149: Oil leak (battery bay) Need parts, REPAIR HYD OIL LEAK @ BATTERY BAY
- DT0150: gears faulty @ battery bay
- FL0099: Coolant Leak- B/Bay, BMS error - Not starting
- FL0107: Bucket - Boilershop
- FL0113: TCU Cut off and transmission clutch pressure low

Key Battery Themes:

- Oil and coolant leaks are common at battery bay locations.
- Recurring gear, transmission, and battery connection/BMS faults cause significant downtime.

None reported.